## **Revision Date - 09/24/2021**

# **FACILITY CONDITION ASSESSMENT**

Dresden Elementary School | 2021





## **Executive Summary**

Dresden Elementary School is located at 2449 Dresden Drive in Atlanta, GA. It comprises 69,760 gross square feet. At the time of the assessment the oldest building was 57 years old.

The findings contained within this report are the result of an assessment of building systems performed by building professionals experienced in disciplines including architecture, mechanical, plumbing and electrical. Only those systems that were identified as having either an associated deficiency or life cycle event within a 10-year window is contained within this report. The full list of each school's systems that are present along with the associated priorities can be found in the flat file data grids submitted to Dekalb County. The projected replacement year of those assets within each system is also included within this table. The total current deficiencies for this site, in 2020 construction cost dollars, are estimated at \$5,222,208. A ten-year need was developed to provide an understanding of the current need as well as the projected needs in the near future. For Dresden Elementary School the ten-year need is \$11,494,008.

For planning purposes, the total current deficiencies and the first five years of projected life cycle needs were combined to calculate a Facility Condition Index (FCI). A 5-year FCI was calculated by dividing the 5-year need by the total replacement cost. Costs associated with new construction are not included in the FCI calculation. After the 5-year FCI was calculated, this value was subtracted from 100 to calculate the FCA Score in a similar fashion to report cards.

The Dresden Elementary School facility has a FCA score of 58.97% which is considered "Poor".

## **Summary of Findings**

The table below summarizes the condition findings at Dresden Elementary School.

Table 1: Facility Condition by Building

Number	Building Name	Current Deficiencies	5-Year Life Cycle Cost	Yrs 6-10 Life Cycle Cost	Total 5 Yr Need (Yr 1-5 + Current Defs)	Total 10 Yr Need (Yr 1-10 + Current Defs)	Replacement Cost	FCA Score
Exterior Si	ite							
	Exterior Site	\$388,779	\$9,989	\$79,965	\$398,767	\$478,733		
Permanen	t Building(s)	-	-		-	-	•	
2010	Building 2010	\$2,861,491	\$924,291	\$1,504,123	\$3,785,782	\$5,289,905	\$8,689,919	56.43%
2011	Building 2011	\$670,104	\$227,052	\$260,926	\$897,156	\$1,158,082	\$2,276,387	60.59%
2012	Building 2012	\$802,770	\$168,112	\$418,565	\$970,883	\$1,389,448	\$2,517,612	61.44%
2013	Building 2013	\$471,851	\$1,218,100	\$824,576	\$1,689,950	\$2,514,526	\$4,339,553	61.06%
2020	Building 2020	\$27,214	\$167,001	\$469,099	\$194,215	\$663,314	\$1,518,885	87.21%
	Sub Total for Permanent Building(s):	\$4,833,430	\$2,704,557	\$3,477,289	\$7,537,986	<i>\$11,015,276</i>	\$19,342,355	
	Total for Site:	\$5,222,208	\$2,714,546	\$3,557,255	\$7,936,754	\$11,494,008	\$19,342,355	58.97%

 $Note \ 1: Sitework \ improvements \ are \ proportionally \ incorporated \ into \ the \ building \ CRV \ and \ used \ to \ calulate \ the \ overall \ FCA \ Score.$ 

Note 2: Aerial map including building number, gross SF, and year built of each building on the site is found on Page 3.



## **Aerial Images**





## **Approach and Methodology**

The facility condition assessment includes a visual assessment of building systems that are readily available during a facility walk-through. The standard process does not reflect invasive, destructive assessment methods that would require special equipment, testing or scheduled power outages. The assessment was accomplished with a view toward identifying significant maintenance and repair deficiencies that need correction. For the purposes of this assessment, deficient conditions captured were limited to those items that did not qualify as routine maintenance repairs. Copies of previous reports and other documentation that were relevant to the inspection were utilized if made available in the process. Additionally, feedback from appropriate personnel to provide background information relative to specific building operations, function, equipment conditions, past improvements and planned upgrades were incorporated into the results if made available to the teams while on site. Two components of the facility condition assessment are combined to total the cost for facility need. The two components of the facility condition assessment are current deficiencies and life cycle forecast.

**Current Deficiencies:** Deficiencies are items in need of repair or replacement as a result of being broken, obsolete, deferred maintenance, or beyond useful life. The existing deficiencies that currently require correction are identified and assigned a priority. An example of a current deficiency might include a broken lighting fixture or an inoperable roof top air conditioning unit.

Life Cycle Forecast: Life cycle analysis evaluates the ages of a building's systems to forecast system replacement as they reach the end of serviceable life. Estimated Useful Lives were determined based on a combination of our (Jacobs) professional experience, RS Means, and from industry standard tables (BOMA, ASHRAE). An example of a life cycle system replacement is a roof with a 20-year life that has been in place for 15 years and may require replacement in five years.

All members of the survey team recorded existing conditions, identified problems and deficiencies, and documented corrective action and quantities. The team took digital photos at each site to better identify significant deficiencies.

## **Facility Deficiency Priority Levels**

Deficiencies were ranked according to five priority levels, with Priority 1 items being the most critical to address:

**Priority 1** – **Mission Critical Concerns:** Deficiencies or conditions that may directly affect the site's ability to remain open or deliver the educational curriculum. These deficiencies typically relate to building safety, code compliance, severely damaged or failing building components, and other items that require near-term correction. An example of a Priority 1 deficiency is a fire alarm system replacement.

**Priority 2 - Indirect Impact to Educational Mission:** Items that may progress to a Priority 1 item if not addressed in the near term. Examples of Priority 2 deficiencies include inadequate roofing that could cause deterioration of integral building systems, and conditions affecting building envelopes, such as roof and window replacements.

**Priority 3 - Short-Term Conditions:** Deficiencies that are necessary to the site's mission but may not require immediate attention. These items should be considered necessary improvements required to maximize facility efficiency and usefulness. Examples of Priority 3 items include site improvements and plumbing deficiencies.


**Priority 4 - Long-Term Requirements:** Items or systems that may be considered improvements to the instructional environment. The improvements may be aesthetic or provide greater functionality. Examples include cabinets, finishes, paving, removal of abandoned equipment, and educational accommodations associated with special programs.

**Priority 5 - Enhancements:** Deficiencies aesthetic in nature or considered enhancements. Typical deficiencies in this priority include repainting, replacing carpet, improved signage, or other improvements to the facility environment.




## Facility Condition Assessment(FCA) Score

Facility Condition Assessment (FCA) Scores are assigned after the Facility Condition Index (FCI) is calculated. The Facility Condition Index (FCI) is used throughout the facility condition assessment industry as a general indicator of a building's health. Since 1991, the facility management industry has used an index called the FCI to benchmark the relative condition of a group of sites. The FCI is derived by dividing the total repair cost, including site-related repairs, by the total replacement cost of all buildings. It should be noted that costs in the New Construction category are not included in the FCI calculation. In an effort to match the report card metrics, the FCI is subtracted from 100 to assign the FCA Score. A facility with a lower FCA Score has more need, or higher priority, than a facility with a higher FCA Score.



The replacement value represents the estimated cost of replacing the current building with another building of like size, based on 2021 estimated cost of construction in the DeKalb County area. The estimated replacement cost for this facility is \$19,342,355. For planning purposes, the total 5-year need at the Dresden Elementary School is \$7,936,754 (Life Cycle Years 1-5 plus the current FCI deficiency cost).

The Dresden Elementary School facility has an FCA Score of 58.97%. which is considered "Poor".





The following table summarizes this site's current deficiencies by building system and priority.

Table 2: System by Priority (Site & Permanent Buildings)

			Priority				
System	1	2	3	4	5	Total	% of Total
Site	\$0	\$0	\$297,384	\$75,107	\$0	\$372,490	7.13 %
Roofing	\$0	\$0	\$874	\$1,613	\$0	\$2,487	0.05 %
Structural	\$0	\$0	\$0	\$0	\$0	\$0	0.00 %
Exterior	\$0	\$717,900	\$47,966	\$0	\$0	\$765,866	14.67 %
Interior	\$0	\$0	\$367,625	\$113,318	\$0	\$480,943	9.21 %
Mechanical	\$0	\$1,177,259	\$216,219	\$179,646	\$6,991	\$1,580,116	30.26 %
Electrical	\$0	\$142,956	\$974,821	\$0	\$0	\$1,117,777	21.40 %
Plumbing	\$0	\$0	\$304,662	\$12,424	\$0	\$317,086	6.07 %
Fire and Life Safety	\$353,433	\$0	\$0	\$0	\$0	\$353,433	6.77 %
Conveyances	\$0	\$0	\$0	\$0	\$0	\$0	0.00 %
Specialties	\$0	\$0	\$303	\$231,707	\$0	\$232,010	4.44 %
Total:	\$353,433	\$2,038,115	\$2,209,855	\$613,814	\$6,991	\$5,222,208	

The building systems at the site with the most need include:

Mechanical	-	\$1,580,116
Electrical	-	\$1,117,777
Exterior	-	\$765,866



The chart below represents the building systems and associated deficiency costs.




Figure 2: System Deficiencies



## **Life Cycle Capital Renewal Forecast**

During the facility condition assessment, assessors inspected all major building systems. If an assessor identified a need for immediate replacement, a deficiency was created with the item's repair costs. The identified deficiency contributes to the facility's total current repair costs.

However, capital planning scenarios span multiple years, as opposed to being constrained to immediate repairs. Construction projects may begin several years after the initial facility condition assessment. Therefore, in addition to the current year repair costs, it is necessary to forecast the facility's future costs using a ten-year life cycle renewal forecast model.

Life cycle renewal is the projection of future building system costs based upon each individual system's expected serviceable life. Building systems and components age over time, eventually break down, reach the end of their useful lives, and may require replacement. While an item may be in good condition now, it might reach the end of its life before a planned construction project occurs.

The following tables show ten-year life cycle capital renewal projections. The projections outline costs for major building systems in which a component is expected to reach the end of its useful life and require capital funding for replacement.

Table 3a: Capital Renewal Forecast (Yrs 1-5)

-	,					
		Life Cycl	e Capital Renewal Pro	ojections		
System	Year 1 2022	Year 2 2023	Year 3 2024	Year 4 2025	Year 5 2026	Total 1-5
Site	\$0	\$0	\$0	\$9,989	\$0	\$9,989
Roofing	\$0	\$0	\$0	\$0	\$587,926	\$587,926
Exterior	\$0	\$0	\$0	\$0	\$20,202	\$20,202
Interior	\$0	\$0	\$132,554	\$0	\$452,057	\$584,611
Mechanical	\$0	\$0	\$11,498	\$268,515	\$149,960	\$429,973
Electrical	\$0	\$0	\$0	\$53,086	\$27,243	\$80,329
Plumbing	\$0	\$0	\$21,330	\$190,498	\$72,671	\$284,499
Fire and Life Safety	\$0	\$0	\$0	\$717,018	\$0	\$717,018
Conveyances	\$0	\$0	\$0	\$0	\$0	\$0
Specialties	\$0	\$0	\$0	\$0	\$0	\$0
Total	\$0	\$0	\$165,382	\$1,239,105	\$1,310,058	\$2,714,546



Table 3b: Capital Renewal Forecast (Yrs 6-10)

			Life Cycle	Capital Renewal I	Projections			
System	Total 1-5	Year 6 2027	Year 7 2028	Year 8 2029	Year 9 2030	Year 10 2031	Total 6-10	Total 1-10
Site	\$9,989	\$0	\$0	\$56,917	\$0	\$0	\$56,917	\$66,906
Roofing	\$587,926	\$0	\$0	\$325,312	\$0	\$23,048	\$348,360	\$936,286
Exterior	\$20,202	\$49,012	\$0	\$3,767	\$0	\$0	\$52,780	\$72,981
Interior	\$584,611	\$108,727	\$0	\$230,263	\$135,827	\$131,232	\$606,049	\$1,190,660
Mechanical	\$429,973	\$224,327	\$0	\$62,808	\$0	\$0	\$287,134	\$717,107
Electrical	\$80,329	\$0	\$0	\$201,123	\$0	\$1,190,368	\$1,391,491	\$1,471,820
Plumbing	\$284,499	\$0	\$0	\$255,138	\$0	\$270,889	\$526,027	\$810,526
Fire and Life Safety	\$717,018	\$35,964	\$0	\$120,759	\$0	\$0	\$156,722	\$873,740
Conveyances	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
Specialties	\$0	\$5,981	\$0	\$125,794	\$0	\$0	\$131,775	\$131,775
Total	\$2,714,546	\$424,010	\$0	\$1,381,880	\$135,827	\$1,615,538	\$3,557,255	\$6,271,800




Figure 3: Ten Year Capital Renewal Forecast



## **Summary of High Priority Deficiencies**

Priority 1 - Mission Critical Concerns		Cost
Fire Alarm Is Missing		\$181,115
Fire Alarm Replacement		\$172,318
	Total for Priority 1	\$353,433
Priority 2 - Indirect Impact to Educational Mission		Cost
Aluminum Window Replacement		\$20,000
Concrete Pre-Cast Panel Replacement (Bldg SF)		\$82,864
Metal Exterior Door Replacement		\$59,249
Storefront/Curtain Wall Replacement (Bldg SF)		\$552,813
Wood Exterior Door Replacement		\$2,974
Cast Iron Water Boiler Replacement		\$19,693
Ductwork Replacement (SF Basis)		\$583,753
Gas Piping Replacement (SF Basis)		\$62,765
Heat Pump HVAC Component Replacement		\$360,112
HVAC VAV Box Replacement		\$58,273
Infrared Electric Radiant Heater Replacement		\$5,742
Mechanical / HVAC Piping / System Is Beyond Its Useful Life		\$81,758
Thru Wall AC Replacement		\$5,164
Electrical Transformer Replacement		\$5,189
Exterior Electrical Enclosure Replacement		\$55,137
Panelboard Replacement		\$69,801
Switchgear Replacement		\$12,829
	Total for Priority 2	\$2,038,115



## **Deficiency Summary**

(Items below detail the totals referenced in Table 2)

## **Site Level Deficiencies**

#### Site

Deficiency		Category	Otv	UoM	Priority	Repair Cost	ID
	d Walkways Replacement	Capital Renewal	500		3	\$23,819	7243
Note:	Damaged	oaphai Hononai	000	0.	Ü	Ψ20,010	
Asphalt Driveway F	-	Capital Renewal	36,960	SF	3	\$223,449	7239
Note:	Cracked And Beyond Useful Life	ouplial Hollowal	00,000	O.	Ü	Ψ220,110	7200
Asphalt Walks Rep	•	Capital Renewal	8,400	SF	3	\$45,741	7242
Note:	Cracked Play Yard	Capital Nonewal	0,400	0.	0	ψ+3,7+1	1272
Site Requires Civil	•	Deferred	1	LS	3	\$4,248	72/1
one requires or in	Diamage Study	Maintenance	'	LO	3	ψ4,240	1241
Note:	Civil Study Needed At Gym As Soil Is Eroding At Northwest Cor	ner.					
Asphalt Paving Re	surfacing	Deferred Maintenance	17,150	SF	4	\$67,065	7237
Note:	Cracked						
Fencing Replacem	ent (8' - 10' high Chain Link Fence)	Capital Renewal	100	LF	4	\$7,366	7236
Note:	Rusted	·				. ,	
Site Drainage Reg	rading	Deferred Maintenance	500	SF	4	\$676	7240
Note:	Outside Room 4 And Building 2012. Eroded Due To Downspout	Not Tied To Storm Drain.					
		Sub Total for System	7	items		\$372,364	
Electrical						, , , , , ,	
		0.1	0.		D : ::	D : 0 :	
Deficiency		Category		UoM	Priority	Repair Cost	ID
Pole Lighting Repla		Capital Renewal	3	Ea.	3	\$16,414	7235
Note:	Beyond Useful Life - Broken						
Note.	Doyona Coolai Ene Dieken						
Building: 2	•	Sub Total for System al for School and Site Level		items items		\$16,414 \$388,779	
Building: 2	Sub Tota	al for School and Site Level	8	items	Priority	\$388,779	ID
Building: 2 Site Deficiency	Sub Tota	al for School and Site Level Category	<b>8</b> Qty	items UoM	Priority	<b>\$388,779</b> Repair Cost	ID 7250
Building: 2 Site Deficiency Exterior Entry Sign	Sub Tota 2010 - Building 2010  Page At The Building Entry Does Not Meet ADA Requirements	al for School and Site Level	<b>8</b> Qty	items	Priority 3	\$388,779	
Building: 2 Site Deficiency	Sub Tota	al for School and Site Level Category	Qty 1	items UoM	<u>_</u>	<b>\$388,779</b> Repair Cost	
Building: 2 Site Deficiency Exterior Entry Sign	Sub Tota 2010 - Building 2010  Page At The Building Entry Does Not Meet ADA Requirements	Category ADA Compliance	Qty 1	UoM Ea.	<u>_</u>	\$388,779  Repair Cost \$126	
Building: 2 Site Deficiency Exterior Entry Sign Note: Exterior	Sub Tota 2010 - Building 2010  Page At The Building Entry Does Not Meet ADA Requirements	Category ADA Compliance Sub Total for System	Qty 1 1	UoM Ea. items	3	\$388,779  Repair Cost \$126	7250
Building: 2 Site Deficiency Exterior Entry Sign Note:	Sub Tota  2010 - Building 2010  Page At The Building Entry Does Not Meet ADA Requirements  Missing	Category ADA Compliance Sub Total for System Category	Qty 1 1 Qty	UoM Ea.	<u>_</u>	\$388,779  Repair Cost \$126	7250 ID
Building: 2 Site Deficiency Exterior Entry Sign Note:  Exterior Deficiency Aluminum Window	Sub Tota 2010 - Building 2010  Page At The Building Entry Does Not Meet ADA Requirements Missing	Category ADA Compliance Sub Total for System	Qty 1 1 Qty	UoM Ea. items	3 Priority	\$388,779  Repair Cost \$126  \$126  Repair Cost	7250 ID
Building: 2 Site Deficiency Exterior Entry Sign Note:  Exterior Deficiency Aluminum Window Note:	Sub Tota 2010 - Building 2010  Page At The Building Entry Does Not Meet ADA Requirements Missing  Replacement Beyond Useful Life	Category ADA Compliance Sub Total for System  Category Category Capital Renewal	Qty 1 1 Qty 32	UoM Ea. items UoM SF	Priority	\$388,779  Repair Cost \$126  \$126  Repair Cost \$3,200	7250 ID 7264
Building: 2 Site Deficiency Exterior Entry Sign Note:  Exterior Deficiency Aluminum Window Note: Aluminum Window	Sub Tota 2010 - Building 2010  Rage At The Building Entry Does Not Meet ADA Requirements Missing  Replacement Beyond Useful Life Replacement	Category ADA Compliance Sub Total for System Category	Qty 1 1 Qty	UoM Ea. items UoM SF	3 Priority	\$388,779  Repair Cost \$126  \$126  Repair Cost	7250 ID 7264
Building: 2 Site Deficiency Exterior Entry Sign Note:  Exterior Deficiency Aluminum Window Note: Aluminum Window	Sub Tota  2010 - Building 2010  Page At The Building Entry Does Not Meet ADA Requirements Missing  Replacement Beyond Useful Life Replacement Beyond Useful Life	Category ADA Compliance Sub Total for System  Category Capital Renewal Capital Renewal	Qty 1 1 Qty 32 168	UoM Ea. items UoM SF	Priority 2	\$388,779  Repair Cost \$126  \$126  Repair Cost \$3,200  \$16,800	7250 ID 7264 7265
Building: 2 Site Deficiency Exterior Entry Sign Note:  Exterior Deficiency Aluminum Window Note: Aluminum Window	Sub Tota 2010 - Building 2010  Rage At The Building Entry Does Not Meet ADA Requirements Missing  Replacement Beyond Useful Life Replacement	Category ADA Compliance Sub Total for System Category Capital Renewal Capital Renewal Capital Renewal Capital Renewal Off. All Overhands Are Pote	Qty 1 1 Qty 32 168 2,600	UoM Ea. items UoM SF SF	Priority 2 2 2	\$388,779  Repair Cost \$126  \$126  Repair Cost \$3,200  \$16,800  \$45,840	7250 ID 7264 7265 7259
Building: 2 Site Deficiency Exterior Entry Sign Note:  Exterior Deficiency Aluminum Window Note: Aluminum Window Note: Concrete Pre-Cast Note:	Sub Tota  2010 - Building 2010  Page At The Building Entry Does Not Meet ADA Requirements Missing  Replacement Beyond Useful Life Replacement Beyond Useful Life Panel Replacement (Bldg SF) Several Of The Concrete Overhangs Are Crumbling And Breakin That A Structural Study Is Conducted. Some Columns Are Water	Category ADA Compliance Sub Total for System Category Capital Renewal	Qty 1 1 Qty 32 168 2,600 entially Stru	UoM Ea. items UoM SF SF SF ucturally	Priority 2 2 2	\$388,779  Repair Cost \$126  \$126  Repair Cost \$3,200  \$16,800  \$45,840	7250 ID 7264 7265 7259 nded
Building: 2 Site Deficiency Exterior Entry Sign Note:  Exterior Deficiency Aluminum Window Note: Aluminum Window Note: Concrete Pre-Cast	Sub Tota  2010 - Building 2010  Page At The Building Entry Does Not Meet ADA Requirements Missing  Replacement Beyond Useful Life Replacement Beyond Useful Life Panel Replacement (Bldg SF) Several Of The Concrete Overhangs Are Crumbling And Breakin That A Structural Study Is Conducted. Some Columns Are Water	Category ADA Compliance Sub Total for System Category Capital Renewal Capital Renewal Capital Renewal Capital Renewal Off. All Overhands Are Pote	Qty 1 1 Qty 32 168 2,600 entially Stru	UoM Ea. items UoM SF SF	Priority 2 2 2 Comprom	\$388,779  Repair Cost \$126  \$126  Repair Cost \$3,200  \$16,800  \$45,840 ised. Recommendation	7250 ID 7264 7265 7259 nded
Building: 2 Site Deficiency Exterior Entry Sign Note:  Exterior Deficiency Aluminum Window Note: Aluminum Window Note: Concrete Pre-Cast Note: Metal Exterior Doo Note:	Sub Total 2010 - Building 2010  Page At The Building Entry Does Not Meet ADA Requirements Missing  Replacement Beyond Useful Life Replacement Beyond Useful Life Panel Replacement (Bldg SF) Several Of The Concrete Overhangs Are Crumbling And Breakin That A Structural Study Is Conducted. Some Columns Are Water Replacement	Category ADA Compliance Sub Total for System Category Capital Renewal	Qty 1 1 Qty 32 168 2,600 entially Stru	UoM Ea. items UoM SF SF scturally	Priority 2 2 2 Comprom	\$388,779  Repair Cost \$126  \$126  Repair Cost \$3,200  \$16,800  \$45,840 ised. Recommer \$38,337	7250 ID 7264 7265 7259 nded 7266
Building: 2 Site Deficiency Exterior Entry Sign Note:  Exterior Deficiency Aluminum Window Note: Aluminum Window Note: Concrete Pre-Cast Note: Metal Exterior Doo Note: Storefront/Curtain	Sub Total 2010 - Building 2010  Page At The Building Entry Does Not Meet ADA Requirements Missing  Replacement Beyond Useful Life Replacement Beyond Useful Life Panel Replacement (Bldg SF) Several Of The Concrete Overhangs Are Crumbling And Breakin That A Structural Study Is Conducted. Some Columns Are Water Replacement Beyond Useful Life Wall Replacement (Bldg SF)	Category ADA Compliance Sub Total for System Category Capital Renewal Capital Renewal Capital Renewal ADA Compliance Sub Total for System Category Capital Renewal	Qty 1 1 1 Qty 32 168 2,600 entially Stru 11 15,671	UoM Ea. items UoM SF SF scturally Door SF	Priority 2 2 2 Comprom 2	\$388,779  Repair Cost \$126  \$126  Repair Cost \$3,200  \$16,800  \$45,840 ised. Recommer \$38,337	7250 ID 7264 7265 7259 Inded 7266
Building: 2 Site Deficiency Exterior Entry Sign Note:  Exterior Deficiency Aluminum Window Note: Aluminum Window Note: Concrete Pre-Cast Note: Metal Exterior Doo Note: Storefront/Curtain Wood Exterior Doo	Sub Total 2010 - Building 2010  Page At The Building Entry Does Not Meet ADA Requirements Missing  Replacement Beyond Useful Life Replacement Beyond Useful Life Panel Replacement (Bldg SF) Several Of The Concrete Overhangs Are Crumbling And Breakin That A Structural Study Is Conducted. Some Columns Are Water Replacement Beyond Useful Life Wall Replacement (Bldg SF) or Replacement	Category ADA Compliance Sub Total for System Category Capital Renewal Renewal Renewal Renewal Capital Renewal Renewal Renewal	Qty 1 1 1 Qty 32 168 2,600 entially Stru 11 15,671	UoM Ea. items UoM SF SF scturally	Priority 2 2 2 Comprom	\$388,779  Repair Cost \$126  \$126  Repair Cost \$3,200  \$16,800  \$45,840 ised. Recommer \$38,337	7250 ID 7264 7265 7259 Inded 7266
Building: 2 Site Deficiency Exterior Entry Sign Note:  Exterior Deficiency Aluminum Window Note: Aluminum Window Note: Concrete Pre-Cast Note: Metal Exterior Doo Note: Storefront/Curtain	Replacement Beyond Useful Life Panel Replacement (Bldg SF) Several Of The Concrete Overhangs Are Crumbling And Breakir That A Structural Study Is Conducted. Some Columns Are Water Replacement Beyond Useful Life Panel Replacement (Bldg SF) Several Of The Concrete Overhangs Are Crumbling And Breakir That A Structural Study Is Conducted. Some Columns Are Water Replacement Beyond Useful Life Wall Replacement (Bldg SF) Or Replacement Rotten	Category ADA Compliance Sub Total for System Category Capital Renewal Capital Renewal Capital Renewal ADA Compliance Sub Total for System Category Capital Renewal	Qty 1 1 1 Qty 32 168 2,600 entially Stru 11 15,671	UoM Ea. items UoM SF SF acturally Door SF Door	Priority 2 2 2 Comprom 2	\$388,779  Repair Cost \$126  \$126  Repair Cost \$3,200  \$16,800  \$45,840 ised. Recommer \$38,337	ID 7264 7265 7259 nded 7266 7267
Building: 2 Site Deficiency Exterior Entry Sign Note:  Exterior Deficiency Aluminum Window Note: Aluminum Window Note: Concrete Pre-Cast Note: Metal Exterior Doo Note: Storefront/Curtain Wood Exterior Doo Note:	Replacement Beyond Useful Life Panel Replacement (Bldg SF) Several Of The Concrete Overhangs Are Crumbling And Breakir That A Structural Study Is Conducted. Some Columns Are Water Replacement Beyond Useful Life Panel Replacement (Bldg SF) Several Of The Concrete Overhangs Are Crumbling And Breakir That A Structural Study Is Conducted. Some Columns Are Water Replacement Beyond Useful Life Wall Replacement (Bldg SF) Or Replacement Rotten	Category ADA Compliance Sub Total for System Category Capital Renewal	Qty 1 1 Qty 32 168 2,600 entially Stru 11 15,671	UoM Ea. items UoM SF SF scturally Door SF Door	Priority 2 2 2 Comprom 2 2 2	\$388,779  Repair Cost \$126  \$126  Repair Cost \$3,200  \$16,800  \$45,840 ised. Recommer \$38,337  \$356,273 \$2,974	ID 7264 7265 7259 nded 7266 7267



Deficiency		Category	Qty	UoM	Priority	Repair Cost	ID
Access Is Not ADA	Compliant	ADA Compliance	1	Door	3	\$7,252	7253
Note:	Door Knob Non-ADA						
Access Is Not ADA	Compliant	ADA Compliance	2	Door	3	\$14,504	7256
Note:	Door Knobs Non-ADA						
Entry Door Does No	t Have Power Assist Device	ADA Compliance	1	Ea.	3	\$14,892	7252
Note:	Missing At Main Door Exit						
Interior Door Hardwa	are Replacement	Capital Renewal	67	Door	3	\$93,517	7282
Note:	Beyond Useful Life						
Interior Door Replac	ement	Capital Renewal	65	Door	3	\$114,620	7281
Note:	Beyond Useful Life						
Acoustical Ceiling Ti	le Replacement	Capital Renewal	5,955	SF	4	\$32,742	7269
Note:	Beyond Useful Life						
Location	: Cafeteria						
Acoustical Ceiling Ti	le Replacement	Capital Renewal	1,000	SF	4	\$5,498	7270
Note:	Stained	•					
Carpet Flooring Rep	lacement	Capital Renewal	2,507	SF	4	\$29,840	7280
Note:	Beyond Useful Life	·					
Ceiling Grid Replace	•	Capital Renewal	5,955	SF	4	\$23,314	7268
Note:	Beyond Useful Life	·	,			. ,	
	: Cafeteria						
Interior Ceiling Repa		Deferred	2,193	SF	4	\$4,277	7271
micror Coming Nope	9	Maintenance	2,.00	0.	·	Ψ.,=	
Note:	Paint Peeling And Kitchen						
		Sub Total for System	10	items		\$340,457	
Mechanical							
Deficiency		Category	Qty	UoM	Priority	Repair Cost	ID
Cast Iron Water Boil	er Replacement	Capital Renewal	1	Ea.	2	\$19,693	7294
Note:	Mech Room						
Ductwork Replacem	ent (SF Basis)	Capital Renewal	31,341	SF	2	\$376,209	7306
Note:	Throughout						
Gas Piping Replace	ment (SF Basis)	Capital Renewal	31,341	SF	2	\$62,765	7289
Note:	Throughout						
Heat Pump HVAC C	component Replacement	Capital Renewal	25	Ea.	2	\$209,367	7302
Note:	Throughout						
Infrared Electric Rac	liant Heater Replacement	Capital Renewal	1	Ea.	2	\$957	7298
Note:	Kitchen	·					
Infrared Electric Rac	liant Heater Replacement	Capital Renewal	3	Ea.	2	\$2,871	7299
Note:	Throughout	·				. ,	
	Piping / System Is Beyond Its Useful Life	Capital Renewal	31,341	SF	2	\$52,690	7304
Note:	Throughout	·	,			. ,	
Circulation Pump Re	_	Capital Renewal	2	Ea.	3	\$27,042	7305
Note:	Mech Room					, , ,	
	austs/Hoods Replacement	Capital Renewal	8	Ea.	3	\$60,443	7307
Note:	No Roof Access					***,	
Testing And Balanci		Deferred	31,341	SF	3	\$62,765	7303
. 00g /aa.ao.	9	Maintenance	0.,0	0.	· ·	ψοΞ,: σσ	
Note:	Throughout						
Existing Controls Are	e Obsolete	Capital Renewal	31,341	SF	4	\$79,476	7300
Note:	Throughout						
Remove Abandoned	I Equipment	Deferred	2	Ea.	5	\$2,330	7308
		Maintenance					
Note:	Media Center						
		Sub Total for System	12	items		\$956,608	



#### **Electrical**

Liectrical						
Deficiency	Category	Qty	UoM	Priority	Repair Cost	ID
Electrical Transformer Replacement	Capital Renewal	1	Ea.	2	\$5,189	7310
Note: Old, Elec Room						
Panelboard Replacement	Capital Renewal	2	Ea.	2	\$5,231	7311
Note: Old, Elec Room						
Panelboard Replacement	Capital Renewal	7	Ea.	2	\$36,193	7312
Note: Old, Elec Room						
Panelboard Replacement	Capital Renewal	2	Ea.	2	\$23,206	7314
Note: Old, Elec Room						
Switchgear Replacement	Capital Renewal	1	Ea.	2	\$12,829	7309
Note: Old, Elec Room						
Lighting Fixtures Replacement	Capital Renewal	25,071	SF	3	\$432,257	7318
Note: Old Classrooms Old Fl.						
Lightning Protection System Installation	Functional Deficiency	31,341	SF	3	\$23,010	7317
Note: Not Installed						
	Sub Total for System	7	items		\$537,916	
Plumbing						
Deficiency	Category	Qty	UoM	Priority	Repair Cost	ID
Plumbing / Domestic Water Piping System Is Beyond Its Useful Life	Capital Renewal	31,341	SF	3	\$141,126	7290
Note: Throughout						
Sanitary Sewer Piping Replacement	Capital Renewal	31,341	SF	3	\$95,098	7291
Note: Throughout						
Refrigerated Water Cooler Replacement	Capital Renewal	4	Ea.	4	\$8,282	7292
Note: Corridor						
	Sub Total for System	3	items		\$244,506	
Fire and Life Safety						
Deficiency	Category	Qty	UoM	Priority	Repair Cost	ID
Fire Alarm Replacement	Capital Renewal	31,341		1	\$172,318	
Note: Old, Entire Building	·					
	Sub Total for System	1	items		\$172,318	
Specialties						
Deficiency	Category	Otv	UoM	Priority	Repair Cost	ID
Counter Heights Exceed Maximum ADA Height Requirements (Modify Full)	ADA Compliance		LF	3	\$303	7251
Note: No Low Counter Top Available	71571 Compilation	Ü		Ü	φοσο	1201
Replace Cabinetry In Classes/Labs	Capital Renewal	14	Room	4	\$115,853	7283
Note: Beyond Useful Life	Capital Hollowal	• • •	1100111	·	ψ110,000	1200
Note: Boyona oscial Eno	Sub Total for System	2	items		\$116,157	
Sub Total for Bu	uilding 2010 - Building 2010		items		\$2,861,491	
	anding 2010 Danding 2010	-10			<b>\$2,001,401</b>	
Building: 2011 - Building 2011						
Exterior						
Deficiency	Category	Qty	UoM	Priority	Repair Cost	ID
Concrete Pre-Cast Panel Replacement (Bldg SF)	Capital Renewal	1,080	SF	2	\$19,041	7324
Note: Several Of The Concrete Overhands Are Crumbling And Breaki That A Structural Study Is Conducted. Come Columns Are Wate		ntially Stru	ucturally	Comprom	ised. Recomme	ended
Storefront/Curtain Wall Replacement (Bldg SF)	Capital Renewal	4,105	SF	2	\$93,325	7325
Note: Beyond Useful Life						
Brick Exterior Repointing	Deferred Maintenance	1,500	SF Wall	3	\$8,994	7326
Note: Eroded Mortar						
	Sub Total for System	3	items		\$121,360	
Interior						
Deficiency	Category	Qty	UoM	Priority	Repair Cost	ID
Interior Door Hardware Replacement	Capital Renewal	12	Door	3	\$16,749	7330
·						



Deficiency		Category	Qty	UoM	Priority	Repair Cost	ID
Interior Door Replac	cement	Capital Renewal	12	Door	3	\$21,161	7329
Note:	Beyond Useful Life						
		Sub Total for System	2	items		\$37,910	
Mechanical							
Deficiency		Category	Qtv	UoM	Priority	Repair Cost	ID
Ductwork Replacem	ent (SF Basis)	Capital Renewal	8,210		2	\$98,551	7341
Note:	Throughout		-,			****	
	Component Replacement	Capital Renewal	9	Ea.	2	\$75,372	7334
Note:	Throughout					* -,-	
	diant Heater Replacement	Capital Renewal	1	Ea.	2	\$957	7332
Note:	Storage 21.6				_	****	
	Piping / System Is Beyond Its Useful Life	Capital Renewal	8,210	SF	2	\$13,803	7339
Note:	Throughout	Capital Helional	0,2.0	0.	_	ψ.ο,σσσ	
Testing And Balanci	-	Deferred	8,210	SF	3	\$16,442	7337
resting raid Balanci	ing	Maintenance	0,210	Oi.	J	Ψ10,442	7007
Note:	Throughout						
Existing Controls Ar	e Obsolete	Capital Renewal	8,210	SF	4	\$20,819	7333
Note:	Throughout						
		Sub Total for System	6	items		\$225,943	
Electrical							
Deficiency		Category	Otv	UoM	Priority	Repair Cost	ID
	nclosure Replacement	Deferred		Ea.	2	\$55,137	_
Exterior Electrical El	noiosure replacement	Maintenance	02	La.	_	ψ55,157	7040
Note:	Not Installed						
Panelboard Replace	ement	Capital Renewal	1	Ea.	2	\$5,170	7342
Note:	Old, Elec Room						
Lighting Fixtures Re	placement	Capital Renewal	6,568	SF	3	\$113,241	7347
Note:	Old FI In Crs						
		Sub Total for System	3	items		\$173,549	
Fire and Life	Safety						
Deficiency	<b>-</b>	Category	Otv	UoM	Priority	Repair Cost	ID
Fire Alarm Is Missin	α	Capital Renewal	8,210		1 Honly	\$45,140	
Note:	9 Old, Entire Building	Capital Nellewal	0,210	Oi	'	ψ+3,1+0	7 544
Note.	Old, Entire Building	Sub Total for System	1	items		\$45,140	
0		Sub Total for System	ı	ILCIIIS		\$45,140	
Specialties							
Deficiency		Category	Qty	UoM	Priority	Repair Cost	ID
Replace Cabinetry I		Capital Renewal	8	Room	4	\$66,202	7331
Note:	Beyond Useful Life						
		Sub Total for System	1	items		\$66,202	
		Sub Total for Building 2011 - Building 2011	16	items		\$670,104	
<b>Building: 2</b>	012 - Building 2012						
Exterior	•						
		2.1	0.		D: ::	D : 0 :	
Deficiency		Category		UoM	Priority	Repair Cost	ID
	Panel Replacement (Bldg SF)	Capital Renewal	1,020	SF	2	\$17,983	7348
Note:	See Note For Building 2010					•	
Metal Exterior Door		Capital Renewal	6	Door	2	\$20,911	7352
Note:	Beyond Useful Life						
Storefront/Curtain W	/all Replacement (Bldg SF)	Capital Renewal	4,540		2	\$103,215	7350
Brick Exterior Repoi	nting	Deferred Maintenance	1,500		3	\$8,994	7351
Note:	Freded Morter	Maintenance		Wall			
NOIE.	Eroded Mortar						
110101		Sub Total for System		items		\$151,103	



	<u>-</u> .					
Deficiency	Category		UoM	Priority	Repair Cost	ID
Interior Door Hardware Replacement	Capital Renewal	28	Door	3	\$39,082	7357
Note: Beyond Useful Life	0. 11. 1		_		<b>4.5.40</b>	
Interior Door Replacement	Capital Renewal	26	Door	3	\$45,848	7355
Note: Beyond Useful Life	0.1.7.4.1604	_	•• • • • •		404.000	
	Sub Total for System	2	items		\$84,930	
Mechanical						
Deficiency	Category	Qty	UoM	Priority	Repair Cost	ID
Ductwork Replacement (SF Basis)	Capital Renewal	9,080	SF	2	\$108,994	7368
Note: Throughout						
Heat Pump HVAC Component Replacement	Capital Renewal	9	Ea.	2	\$75,372	7365
Note: Throughout						
Infrared Electric Radiant Heater Replacement	Capital Renewal	1	Ea.	2	\$957	7363
Note: Corridor						
Mechanical / HVAC Piping / System Is Beyond Its Useful Life	Capital Renewal	9,080	SF	2	\$15,265	7367
Note: Throughout						
Testing And Balancing	Deferred	9,080	SF	3	\$18,184	7366
	Maintenance					
Note: Throughout		_	_			
Ceiling Exhaust Fan Replacement	Capital Renewal	6	Ea.	4	\$2,745	7369
Note: Restrooms						
Existing Controls Are Obsolete	Capital Renewal	9,080	SF	4	\$23,025	7364
Note: Throughout						
Remove Abandoned Equipment	Deferred Maintenance	4	Ea.	5	\$4,661	7370
Note: Unit Ventilators In Classrooms	Waintenance					
Note. Offit ventuators in Glassicoms	Sub Total for System		items		\$249,204	
Floatrical	Sub rotal for System	0	ILEIIIS		\$245,204	
Electrical						
Deficiency	Category		UoM	Priority	Repair Cost	ID
Canopy Lighting Replacement	Capital Renewal	1	Ea.	3	\$1,958	7373
Note: Old, Canopy						
Lighting Fixtures Replacement	Capital Renewal	8,172	SF	3	\$140,896	7374
Note: Old, Classrooms						
Lightning Protection System Installation	Functional Deficiency	9,080	SF	3	\$6,666	7372
Note: Not Installed						
	Sub Total for System	3	items		\$149,521	
Plumbing						
Deficiency	Category	Qty	UoM	Priority	Repair Cost	ID
Plumbing / Domestic Water Piping System Is Beyond Its Useful Life	Capital Renewal	9,080	SF	3	\$40,886	7361
Note: Throughout						
Sanitary Sewer Piping Replacement	Capital Renewal	9,080	SF	3	\$27,552	7362
Note: Throughout						
	Sub Total for System	2	items		\$68,438	
Fire and Life Safety						
-	Catagony	Otv	UoM	Priority	Repair Cost	ID
Deficiency Fire Alarm Is Missing	Category Capital Renewal	9,080		1	\$49,923	7371
•	Capital Kellewal	9,000	OI .		φ49,923	7371
Note: Old, Entire Building	Sub Total for Sustam				¢40.022	
	Sub Total for System	1	items		\$49,923	
Specialties						
Deficiency	Category	Qty	UoM	Priority	Repair Cost	ID
Replace Cabinetry In Classes/Labs	Capital Renewal	6	Room	4	\$49,651	7358
Note: Beyond Useful Life						
	Sub Total for System	1	items		\$49,651	

## **Building: 2013 - Building 2013**

Deficiency		Category	Qty	UoM	Priority	Repair Cost	ID
Vinyl Composition T	ile Replacement	Capital Renewal	2,000	SF	4	\$15,997	7375
Note:	Damaged And Worn Out						
		Sub Total for System	1	items		\$15,997	
Mechanical							
Deficiency		Category	Qty	UoM	Priority	Repair Cost	ID
HVAC VAV Box Re	placement	Capital Renewal		Ea.	2	\$58,273	7379
Note:	Throughout	·					
Testing And Balanc	-	Deferred Maintenance	15,651	SF	3	\$31,343	7378
Note:	Throughout						
Existing Controls Ar	e Obsolete	Capital Renewal	15,651	SF	4	\$39,689	1042
		Sub Total for System	3	items		\$129,305	
Electrical							
Deficiency		Category	Otv	UoM	Priority	Repair Cost	ID
Canopy Lighting Re	polacement	Capital Renewal		Ea.	3	\$3,917	
Note:	Old, Exterior	Oapital Nellewal	2	La.	3	ψ5,517	7 302
	uilding Lighting Replacement	Capital Renewal	6	Ea.	3	\$5,087	7202
Note:	Old, Exterior	Capital Nellewal	U	La.	3	φ5,067	7300
		Capital Renewal	12 520	ee.	3	\$24E 964	7205
Lighting Fixtures Re		Capital Reflewal	12,520	SF	3	\$215,861	7385
Note:	Old, Classroom Fl	Franking - I Defining a	45.054	0.	•	¢44.404	7004
	System Installation	Functional Deficiency	15,651	SF	3	\$11,491	7381
Note:	Not Installed					****	
		Sub Total for System	4	items		\$236,356	
Plumbing							
Deficiency		Category	Qty	UoM	Priority	Repair Cost	ID
Refrigerated Water	Cooler Replacement	Capital Renewal	2	Ea.	4	\$4,141	7377
Note:	Corridor						
		Sub Total for System	1	items		\$4,141	
Fire and Life	Safety						
Deficiency	-	Category	Qty	UoM	Priority	Repair Cost	ID
Fire Alarm Is Missin	g	Capital Renewal	15,651	SF	1	\$86,052	7380
Note:	Old Entire Building						
	Old, Entire Building						
	Ola, Entire Building	Sub Total for System	1	items		\$86,052	
	Old, Entire Building	· · · · · · · · · · · · · · · · · · ·		items items		\$86,052 \$471,851	
Building: 2		Sub Total for System Sub Total for Building 2013 - Building 2013					
•	2020 - Building 2020	· · · · · · · · · · · · · · · · · · ·					
•		· · · · · · · · · · · · · · · · · · ·					
•		· · · · · · · · · · · · · · · · · · ·	10		Priority		ID
Roofing Deficiency	2020 - Building 2020	Sub Total for Building 2013 - Building 2013  Category  Deferred	10	items UoM	Priority 3	\$471,851	
Roofing Deficiency Debris In Gutter Rec	2020 - Building 2020	Sub Total for Building 2013 - Building 2013  Category	<b>10</b> Qty	items UoM		<b>\$471,851</b> Repair Cost	
Roofing Deficiency Debris In Gutter Rei Note:	2020 - Building 2020	Sub Total for Building 2013 - Building 2013  Category  Deferred Maintenance	Qty 180	UoM LF	3	\$471,851  Repair Cost \$874	7400
Roofing Deficiency Debris In Gutter Rei Note:	2020 - Building 2020	Sub Total for Building 2013 - Building 2013  Category  Deferred Maintenance  Deferred	<b>10</b> Qty	UoM LF		<b>\$471,851</b> Repair Cost	7400
Roofing Deficiency Debris In Gutter Rec Note: Roof Cleaning	2020 - Building 2020  moval  Debris And Trees Growing	Sub Total for Building 2013 - Building 2013  Category  Deferred Maintenance	Qty 180	UoM LF	3	\$471,851  Repair Cost \$874	7400
Roofing Deficiency Debris In Gutter Rec Note: Roof Cleaning Note:	2020 - Building 2020  moval  Debris And Trees Growing  Weathered	Sub Total for Building 2013 - Building 2013  Category  Deferred Maintenance  Deferred Maintenance	10 Qty 180 6,848	UoM LF SF	3	\$471,851  Repair Cost \$874  \$1,496	7400
Roofing Deficiency Debris In Gutter Rec Note: Roof Cleaning Note:	2020 - Building 2020  moval  Debris And Trees Growing  Weathered	Sub Total for Building 2013 - Building 2013  Category  Deferred Maintenance  Deferred	10 Qty 180 6,848	UoM LF	3	\$471,851  Repair Cost \$874  \$1,496	7400
Roofing Deficiency Debris In Gutter Rec Note: Roof Cleaning Note:	2020 - Building 2020  moval  Debris And Trees Growing  Weathered	Sub Total for Building 2013 - Building 2013  Category  Deferred Maintenance  Deferred Maintenance  Deferred	10 Qty 180 6,848	UoM LF SF	3	\$471,851  Repair Cost \$874  \$1,496	7400
Roofing Deficiency Debris In Gutter Rei Note: Roof Cleaning Note: Splash Block Repla	moval Debris And Trees Growing  Weathered cement	Sub Total for Building 2013 - Building 2013  Category  Deferred Maintenance  Deferred Maintenance  Deferred	10 Qty 180 6,848	UoM LF SF	3	\$471,851  Repair Cost \$874  \$1,496	7400
Roofing Deficiency Debris In Gutter Rei Note: Roof Cleaning Note: Splash Block Repla Note:	moval Debris And Trees Growing  Weathered cement	Sub Total for Building 2013 - Building 2013  Category  Deferred Maintenance  Deferred Maintenance  Deferred Maintenance	10 Qty 180 6,848	UoM LF SF Ea.	3	\$471,851  Repair Cost \$874  \$1,496  \$117	7400
Roofing Deficiency Debris In Gutter Ref Note: Roof Cleaning Note: Splash Block Replation Note: Interior	moval Debris And Trees Growing  Weathered cement	Category Deferred Maintenance Deferred Maintenance Deferred Maintenance Sub Total for System	10 Qty 180 6,848 2	UoM LF SF Ea.	4	\$471,851  Repair Cost \$874  \$1,496  \$117  \$2,487	7400 7398 7401
Roofing Deficiency Debris In Gutter Ref Note: Roof Cleaning Note: Splash Block Replation Note: Interior Deficiency	moval  Debris And Trees Growing  Weathered cement  Worn Out	Category  Deferred Maintenance  Deferred Maintenance  Deferred Maintenance  Sub Total for System  Category	Qty 180 6,848 2 3	UoM LF SF Ea. items	3 4 4 Priority	\$471,851  Repair Cost \$874  \$1,496  \$117  \$2,487  Repair Cost	7400 7398 7401
Roofing Deficiency Debris In Gutter Rei Note: Roof Cleaning Note: Splash Block Replation Note: Interior Deficiency Acoustical Ceiling T	moval Debris And Trees Growing  Weathered cement Worn Out	Category Deferred Maintenance Deferred Maintenance Deferred Maintenance Sub Total for System	10 Qty 180 6,848 2	UoM LF SF Ea. items	4	\$471,851  Repair Cost \$874  \$1,496  \$117  \$2,487	7400 7398 7401
Roofing Deficiency Debris In Gutter Rei Note: Roof Cleaning Note: Splash Block Repla	moval  Debris And Trees Growing  Weathered cement  Worn Out	Category  Deferred Maintenance  Deferred Maintenance  Deferred Maintenance  Sub Total for System  Category	10 Qty 180 6,848 2 Qty 300	UoM LF SF Ea. items	3 4 4 Priority	\$471,851  Repair Cost \$874  \$1,496  \$117  \$2,487  Repair Cost	7400 7398 7401



## **Facility Condition Assessment**

DeKalb County SD - Dresden Elementary School

#### Mechanical

Deficiency	Category	Qty UoM	Priority	Repair Cost	ID
Thru Wall AC Replacement	Capital Renewal	1 Ea.	2	\$5,164	7402
Note: Coach Office					
Existing Controls Are Obsolete	Capital Renewal	5,478 SF	4	\$13,891	10429
	Sub Total for System	2 items		\$19,056	
Electrical					
Deficiency	Category	Qty UoM	Priority	Repair Cost	ID
Lightning Protection System Installation	Functional Deficiency	5,478 SF	3	\$4,022	7407
Note: Not Installed					
	Sub Total for System	1 items		\$4,022	
	Sub Total for Building 2020 - Building 2020	7 items		\$27,214	
	Total for Campus	105 items		\$5,222,208	

Repair Cost Remaining Life



## Life Cycle Summary Yrs 1-10

(Items below detail the totals referenced in Tables 3a & 3b)

LC Type Description

#### Site Level Life Cycle Items

#### Site

Uniformat Description	LC Type Description	Priority	Qty UoM	Repair Cost	Remaining Life
Fences and Gates	Fencing - Chain Link (4 Ft)	3	200 LF	\$9,989	4
Fences and Gates	Fencing - Chain Link (8-10 Ft)	3	610 LF	\$56,917	8
		Sub Total for System	2 items	\$66,906	
Roofing					
Uniformat Description	LC Type Description	Priority	Qty UoM	Repair Cost	Remaining Life
Canopy Roofing	Aluminum panels	4	360 SF	\$23,048	10
		Sub Total for System	1 items	\$23,048	
		Sub Total for Building -	3 items	\$89,954	

#### Building: 2010 - Building 2010

#### **Exterior**

Uniformat Description

Exterior Entrance Doors	Wooden Door	3	1 Door	\$3,767 8
		Sub Total for System	1 items	\$3,767
Interior				
Uniformat Description	LC Type Description	Priority	Qty UoM	Repair Cost Remaining Life
Acquetical Suspended Coilings	Coilings - Acquetical Tiles		21 625 SE	\$120,022 3

Qty UoM

Priority

Uniformat Description	LC Type Description	Priority	Qty	UoM	Repair Cost	Remaining Life
Acoustical Suspended Ceilings	Ceilings - Acoustical Tiles	4	21,625	SF	\$129,923	3
Wall Paneling	Wood Panel wall	4	313	SF	\$5,350	5
Resilient Flooring	Vinyl Composition Tile Flooring	4	17,238	SF	\$159,837	5
Acoustical Suspended Ceilings	Ceilings - Acoustical Grid System	4	21,625	SF	\$101,093	6
Carpeting	Carpet	4	2,507	SF	\$37,800	8
Acoustical Suspended Ceilings	Ceilings - Acoustical Tiles	4	5,955	SF	\$44,003	10
Suspended Plaster and	Painted ceilings	5	3,134	SF	\$8,246	10
Compartments and Cubicles	Toilet Partitions	4	31	Stall	\$78,983	10
		Sub Total for System	8	items	\$565,236	

#### **Mechanical**

Uniformat Description	LC Type Description	Priority	Qty UoM	Repair Cost Remaining Life
Exhaust Air	Kitchen Exhaust Hoods	3	1 Ea.	\$11,498 3
Decentralized Cooling	Condenser - Inside Air Cooled (3 ton)	2	1 Ea.	\$6,796 4
Decentralized Cooling	Ductless Split System (3 Ton)	2	1 Ea.	\$5,740 4
HVAC Air Distribution	Roof Top Unit - DX Gas (5 Ton)	2	1 Ea.	\$16,834 4
	Note: No roof access			
HVAC Air Distribution	Roof Top Unit - DX Gas (5 Ton)	2	1 Ea.	\$16,834 4
	Note: No roof access			
Heat Generation	Steam Condensate Receiver, Tank and Pump	2	5 Ea.	\$80,502 4
Exhaust Air	Interior Ceiling Exhaust Fan	3	2 Ea.	\$1,061 5
Central Cooling	Cooling Tower - Metal (130 Tons)	2	1 Ea.	\$59,171 8
		Sub Total for System	8 items	\$198,436

## **Electrical**

Uniformat Description	LC Type Description	Priority	Qty UoM	Repair Cost Remaining Life
Audio-Video Systems	PA Communications No Head Unit (Bldg SF)	2	31,341 SF	\$23,476 4
	Note: Entire bldg			
Lighting Fixtures	Building Mounted Fixtures (Ea.)	4	8 Ea.	\$7,633 4
	Note: Exterior			
Lighting Fixtures	Canopy Mounted Fixtures (Ea.)	4	12 Ea.	\$27,243 5
	Note: Exterior			
Electrical Service	Transformer (45 KVA)	2	1 Ea.	\$7,050 8
	Note: Elec room			
Electrical Service	Transformer (75 KVA)	2	2 Ea.	\$17,359 8
	Note: Elec room			
Power Distribution	Panelboard - 120/208 225A	3	10 Ea.	\$65,498 8

#### **Electrical**

Liectrical							
Uniformat Description		LC Type Description	Priority	Qty	UoM	Repair Cost	Remaining Life
Power Distribution		Panelboard - 277/480 100A	3	1	Ea.	\$7,965	8
	Note:	Elec room					
Power Distribution		Panelboard - 277/480 225A	3	2	Ea.	\$22,324	8
	Note:	Elec room					
Packaged Generator Assemblies		Emergency Generator (75 KW)	2	1	Ea.	\$63,546	10
	Note:	Exterior					
Lighting Fixtures		Light Fixtures (Bldg SF)	4	31,341	SF	\$726,198	10
			Sub Total for System	10	items	\$968,292	
Plumbing							
Uniformat Description		LC Type Description	Priority	Otv	UoM	Popair Cost	Remaining Life
· · · · · · · · · · · · · · · · · · ·			2		Ea.	\$2,194	3
Domestic Water Equipment		Water Heater - Electric - 30 gallon	2		Ea.		3
Domestic Water Equipment		Water Heater - Electric - 20 gallon	2		Ea.	\$1,630 \$6,550	3
Domestic Water Equipment		Water Heater - Gas - 100 Gallon Water Heater - Gas - 100 Gallon	2		Ea.	\$6,559 \$6,550	3
Domestic Water Equipment						\$6,559	
Plumbing Fixtures		Sink - Service / Mop Sink	5		Ea.	\$842	4
Plumbing Fixtures		Sink - Service / Mop Sink	5		Ea.	\$3,369	4
Plumbing Fixtures		Refrigerated Drinking Fountain	4		Ea.	\$11,652	4
Plumbing Fixtures		Sink - Service / Mop Sink	5		Ea.	\$842	4
Plumbing Fixtures		Sink - Service / Mop Sink	5		Ea.	\$842	4
Plumbing Fixtures		Sink - Service / Mop Sink	5		Ea.	\$842	4
Compressed-Air Systems		Air Compressor (1/2 hp)	3	1	Ea.	\$3,536	4
	Note:	Remove with installation of new controls		_	_		_
Plumbing Fixtures		Classroom Lavatory	4		Ea.	\$22,360	5
Plumbing Fixtures		Restroom Lavatory	3		Ea.	\$61,466	8
Plumbing Fixtures		Toilets	3		Ea.	\$180,768	8
Plumbing Fixtures		Urinals	3		Ea.	\$12,903	8
			Sub Total for System	15	items	\$316,364	
Fire and Life Safety							
Uniformat Description		LC Type Description	Priority	Qty	UoM	Repair Cost	Remaining Life
Security System Component		Security Alarm System	1	31,341	SF	\$370,337	4
	Note:	Entire bldg					
			Sub Total for System	1	items	\$370,337	
Specialties							
=		LC Time Description	Driority	04.	HaM	Danair Cast	Demoining Life
Uniformat Description  Casework		LC Type Description	Priority		UoM		Remaining Life
Casework		Lockers	4		Ea.	\$5,981	6
		Out Total for D	Sub Total for System		items	\$5,981	
		Sub lotal for B	uilding 2010 - Building 2010	44	items	\$2,428,414	
Building: 2011 - Bui	lding	2011					
In Conton							
Interior							
Uniformat Description		LC Type Description	Priority	Qty	UoM	Repair Cost	Remaining Life
Acoustical Suspended Ceilings		Ceilings - Acoustical Tiles	4	8,210	SF	\$52,330	5
Acoustical Suspended Ceilings		Ceilings - Acoustical Tiles	4	8,210	SF	\$52,330	5
Resilient Flooring		Vinyl Composition Tile Flooring	4	6,568	SF	\$68,545	9
			Sub Total for System	3	items	\$173,204	
Mechanical							
Uniformat Description		LC Type Description	Priority	Otv	UoM	Renair Cost	Remaining Life
Decentralized Cooling		Thru-Wall AC (2 Ton)	3		Ea.	\$5,812	4
Exhaust Air		Roof Exhaust Fan - Large	3		Ea.	\$8,758	5
=addt / III	Noto	No roof access	3	'	_u.	ψυ,1 30	3
	14016.	110 100, 000000	Sub Total for System	2	items	¢1/ 570	
Electric 1			Jub Total for System	2	ucill9	\$14,570	
Electrical							
Uniformat Description		LC Type Description	Priority	Qty	UoM	Repair Cost	Remaining Life
Audio-Video Systems		PA Communications No Head Unit (Bldg SF)	2	8,210	SF	\$6,150	4
	Note:	Entire bldg					
Lighting Fixtures		Building Mounted Fixtures (Ea.)	4	2	Ea.	\$2,148	8
Lighting Fixtures		Light Fixtures (Bldg SF)	4	8,210	SF	\$190,233	10
			Sub Total for System	•	itomo	\$100 E21	

\$198,531

3 items

Sub Total for System





	ing

Uniformat Description	LC Type Description	Priority	Qty	UoM	Repair Cost	Remaining Life
Plumbing Fixtures	Refrigerated Drinking Fountain	4	2	Ea.	\$4,661	4
		Sub Total for System	1	items	\$4,661	
Fire and Life Safety	1					
Uniformat Description	LC Type Description	Priority	Qty	UoM	Repair Cost	Remaining Life
Security System Component	Security Alarm System	1	8,210	SF	\$97,012	4
	Note: Entire bldg					
		Sub Total for System	1	items	\$97,012	
	Sub Total fo	r Building 2011 - Building 2011	10	items	\$487,978	
Building: 2012 - Bu	ildina 2012					
•	<b>3</b>					
Interior						
Uniformat Description	LC Type Description	Priority		UoM	Repair Cost	Remaining Life
Acoustical Suspended Ceilings	Ceilings - Acoustical Tiles	4	8,354	SF	\$53,248	5
Tile Flooring	Quarry Tile	4	182	SF	\$5,586	6
Interior Swinging Doors	Metal Door (Steel)	3	2	Door	\$6,892	8
Resilient Flooring	Vinyl Composition Tile Flooring	4	6,447	SF	\$67,282	9
		Sub Total for System	4	items	\$133,008	
Mechanical						
Uniformat Description	LC Type Description	Priority	Qty	UoM	Repair Cost	Remaining Life
Exhaust Air	Roof Exhaust Fan - Large	3	7	Ea.	\$61,312	5
	Note: No roof access					
		Sub Total for System	1	items	\$61,312	
Electrical						
Uniformat Description	LC Type Description	Priority	Qty	UoM	Repair Cost	Remaining Life
Audio-Video Systems	PA Communications No Head Unit (Bldg SF)	2	9,080	SF	\$7,655	8
	Note: Throughout bldg					
Lighting Fixtures	Light Fixtures (Bldg SF)	4	9,080	SF	\$210,391	10
		Sub Total for System	2	items	\$218,046	
Plumbing						
Uniformat Description	LC Type Description	Priority	Qty	UoM	Repair Cost	Remaining Life
Plumbing Fixtures	Toilets	3	6	Ea.	\$32,122	4
	1011010		0	La.	ψ3Z, 1ZZ	

Official Description	LO Type Description	Filolity	Qty Oolvi	Repair Cost Remaining Life
Plumbing Fixtures	Toilets	3	6 Ea.	\$32,122 4
Plumbing Fixtures	Refrigerated Drinking Fountain	4	2 Ea.	\$4,661 4
Plumbing Fixtures	Classroom Lavatory	4	6 Ea.	\$16,770 5
		Sub Total for System	3 items	\$53,553
Fine and Life Cafety	_			

#### Fire and Life Safety

Uniformat Description	LC Type Description	Priority	Qty UoM	Repair Cost Remaining Life
Security System Component	Security Alarm System	1	9,080 SF	\$120,759 8
	Note: Throughout bldg			
		Sub Total for System	1 itoms	\$120.750

Sub Total for Building 2012 - Building 2012

11 items

\$586,678

\$296,128

## Building: 2013 - Building 2013

#### Roofing

Uniformat Description	LC Type Description	Priority	Qty	UoM	Repair Cost	Remaining Life
Low-Slope Roofing	Modified Bitumen	2	15,651	SF	\$587,926	5
		Sub Total for System	1	items	\$587,926	
Exterior						
Uniformat Description	LC Type Description	Priority	Qty	UoM	Repair Cost	Remaining Life
Exterior Entrance Doors	Storefront Doors - Glass/Aluminum	3	11	Door	\$49,012	6
		Sub Total for System	1	items	\$49,012	
Interior						
Uniformat Description	LC Type Description	Priority	Qty	UoM	Repair Cost	Remaining Life
Compartments and Cubicles	Toilet Partitions	4	4	Stall	\$8,791	5
Resilient Flooring	Vinyl Composition Tile Flooring	4	11,738	SF	\$108,840	5
Acoustical Suspended Ceilings	Ceilings - Acoustical Tiles	4	14,712	SF	\$102,468	8
Interior Door Supplementary Components	Door Hardware	3	43	Door	\$76,030	8

Sub Total for System





		cal

Mechanical						
Uniformat Description	LC Type Description	Priority	Qty	UoM	Repair Cost	Remaining Life
HVAC Air Distribution	Roof Top Unit - DX Gas (25 Ton)	2	2	Ea.	\$135,996	4
Exhaust Air	Roof Exhaust Fan - Large	3	6	Ea.	\$52,553	5
No	te: No roof access					
HVAC Air Distribution	Ductwork (Bldg.SF)	3	15,651	SF	\$224,327	6
		Sub Total for System	3	items	\$412,876	
Electrical						
Uniformat Description	LC Type Description	Priority	Otv	UoM	Popair Cost	Remaining Life
Audio-Video Systems	PA Communications No Head Unit (Bldg SF)	2	15,651		\$11,723	4
,	te: Entier bldg	2	13,031	OI .	Ψ11,723	7
Electrical Service	Transformer (75 KVA)	2	1	Ea.	\$8,679	8
	te: Elec room	2		La.	ψ0,073	o
Power Distribution	Panelboard - 120/208 225A	3	2	Ea.	\$13,100	8
	te: Elec room	J	2	La.	ψ13,100	o
Power Distribution	Panelboard - 277/480 100A	3	1	Ea.	\$7,965	8
	te: Elec room	v		Lu.	ψ,,σσσ	Ü
Power Distribution	Panelboard - 277/480 400A	3	1	Ea.	\$16,544	8
	te: Elec room	J		La.	ψ10,544	o
140	e. Lieo room	Sub Total for System	5	items	\$58,011	
Diametria a		oub rotal for dystem	J	items	\$30,011	
Plumbing						
Uniformat Description	LC Type Description	Priority	Qty	UoM	Repair Cost	Remaining Life
Domestic Water Equipment	Water Heater - Electric - 30 gallon	2		Ea.	\$2,194	3
Plumbing Fixtures	Restroom Lavatory	3	5	Ea.	\$14,372	4
Plumbing Fixtures	Sink - Service / Mop Sink	5	1	Ea.	\$842	4
Plumbing Fixtures	Toilets	3	14	Ea.	\$74,951	4
Plumbing Fixtures	Urinals	3	1	Ea.	\$1,433	4
Plumbing Fixtures	Classroom Lavatory	4	12	Ea.	\$33,541	5
Domestic Water Equipment	Gas Piping System (BldgSF)	2	15,651	SF	\$42,122	10
Domestic Water Piping	Domestic Water Piping System (Bldg.SF)	3	15,651	SF	\$94,712	10
Sanitary Sewerage Piping	Sanitary Sewer Piping	2	15,651	SF	\$63,823	10
		Sub Total for System	9	items	\$327,990	
Fire and Life Safety						
Uniformat Description	LC Type Description	Priority	Qty	UoM	Repair Cost	Remaining Life
Security System Component	Security Alarm System	1	15,651		\$184,938	4
, ,	te: Entire bldg					
	Ç	Sub Total for System	1	items	\$184,938	
Specialties		·				
•			_			
Uniformat Description	LC Type Description	Priority		UoM	-	Remaining Life
Casework	Fixed Cabinetry	4		Room	\$125,794	8
		Sub Total for System		items	\$125,794	
	Sub Total for	Building 2013 - Building 2013	25	items	\$2,042,676	
Building: 2020 - Buildin	g 2020					
- ·	_					
Roofing						
Uniformat Description	LC Type Description	Priority	Qty	UoM	Repair Cost	Remaining Life
Steep Slope Roofing	Metal (Architectural - Standing Seam)	2	6,848	SF	\$325,312	8
		Sub Total for System	1	items	\$325,312	
Exterior						
Uniformat Description	LC Type Description	Priority	Qtv	UoM	Repair Cost	Remaining Life
Exterior Entrance Doors	Steel - Insulated and Painted	3		Door	\$20,202	5
		Sub Total for System		items	\$20,202	-
Interior					,	
					_	
Uniformat Description	LC Type Description	Priority	<u>-</u>	UoM		Remaining Life
Acoustical Suspended Ceilings	Ceilings - Acoustical Tiles	4	438		\$2,631	3
Compartments and Cubicles	Toilet Partitions	4		Stall	\$8,791	5
Resilient Flooring	Vinyl Composition Tile Flooring	4	274		\$2,541	5
Acoustical Suspended Ceilings	Ceilings - Acoustical Grid System	4	438		\$2,048	6
Interior Door Supplementary Components	S Door Hardware	3	4	Door	\$7,072	8
		Sub Total for System	5	items	\$23,083	



#### Mechanical

Uniformat Description		LC Type Description	Priority	Qty	UoM	Repair Cost	Remaining Life
Exhaust Air		Roof Exhaust Fan - Large	3	3	Ea.	\$26,276	5
Decentralized Heating Equipment		Radiant Heater - Infrared Electric	3	3	Ea.	\$3,637	8
			Sub Total for System	2	items	\$29,913	
Electrical							
Uniformat Description		LC Type Description	Priority	Qty	UoM	Repair Cost	Remaining Life
Audio-Video Systems		PA Communications No Head Unit (Bldg SF)	2	5,478	SF	\$4,104	4
	Note:	Gym					
Power Distribution		Panelboard - 120/208 225A	3	1	Ea.	\$6,549	8
	Note:	Elec room					
Power Distribution		Panelboard - 277/480 100A	3	1	Ea.	\$7,965	8
	Note:	Elec room					
Electrical Service		Exterior Dry Type Transformer (45 KVA)	2	1	Ea.	\$8,172	8
	Note:	Exterior Gym					
Lighting Fixtures		Building Mounted Fixtures (Ea.)	4	2	Ea.	\$2,148	8
	Note:	Wall exterior					
			Sub Total for System	5	items	\$28,939	
Plumbing							
Uniformat Description		LC Type Description	Priority	Qty	UoM	Repair Cost	Remaining Life
Domestic Water Equipment		Water Heater - Electric - 30 gallon	2	1	Ea.	\$2,194	3
Plumbing Fixtures		Restroom Lavatory	3	2	Ea.	\$5,749	4
Plumbing Fixtures		Sink - Service / Mop Sink	5	1	Ea.	\$842	4
Plumbing Fixtures		Toilets	3	4	Ea.	\$21,415	4
Plumbing Fixtures		Urinals	3	2	Ea.	\$2,866	4
Plumbing Fixtures		Refrigerated Drinking Fountain	4	2	Ea.	\$4,661	4
Domestic Water Equipment		Gas Piping System (BldgSF)	2	5,478	SF	\$14,743	10
Domestic Water Piping		Domestic Water Piping System (Bldg.SF)	3	5,478	SF	\$33,150	10
Sanitary Sewerage Piping		Sanitary Sewer Piping	2	5,478	SF	\$22,339	10
			Sub Total for System	9	items	\$107,958	
Fire and Life Safety							
Uniformat Description		LC Type Description	Priority	Qty	UoM	Repair Cost	Remaining Life
Security System Component		Security Alarm System	1	5,478	SF	\$64,730	4
	Note:	Gym					
Fire Detection and Alarm		Fire Alarm	1	5,478	SF	\$35,964	6
	Note:	Gym					
			Sub Total for System	2	items	\$100,694	
		Sub Total for B	uilding 2020 - Building 2020	25	items	\$636,100	



## **Supporting Photos**



Replace Controls Throughout



Replace Pumps



Replace Boiler



Existing Compressor Can Be Removed When Controls Are Replaced



Replace Panelboards



Replace Main Switchboard





Roof Gutters With Debris And Tree Growing Need To Be Cleaned



Classroom Wood Cabinetry Beyond Useful Life Needs Replacement



Concrete Roof Overhangs With Peeling Paint Need To Be Repainted



Concrete Roof Overhangs Water Damaged And Falling Apart And Need To Be Repaired. Structural Study Recommended To Assess Concrete Structure Condition