

Dekalb County School District (409-36) - Druid Hills High School Modernization Civil Site Assessment

Prepared by Cody Lanman Jan 31, 2024

Description

Druid Hills Highschool Modernization Assessment, Preliminary Civil Site Investigation & observations. The following report documents the existing conditions of the DHHS Campus as it relates to the civil / site considerations.

Contents

#95 Field to Central Courtyard Connection: Drainage & Sidewalks	5
#94 Field Parking Area: Pavement & Drainage	7
#93 Track & Field: Southeastern Drainage & Asphalt	10
#92 Track & Field: Northeastern Drainage & Asphalt	12
#91 Track & Field: Northeastern Drainage & Asphalt	15
#90 Track & Field: Northwestern Drainage & Asphalt	17
#89 Track & Field: Southwestern Drainage & Asphalt	20
#88 Softball Field: Western Drainage	23
#87 1953 Building Eastern Stair Connection	24
#86 1961 Lift Station	26
#85 Field Area Existing Stone Wall	28
#84 Western Courtyard to Lower Building Access: Sidewalk & Drainage	30
#83 Central Campus Pedestrian Connections & Wooded Area	33
#82 Western Courtyard: Drainage & Landscape	36
#81 Central Courtyard: Sidewalks & Drainage	38
#80 Central Courtyard: Drainage & Landscaping	40
#79 Sidewalk Connection to Central Courtyard	42
#78 Bus Drop-off: Exit Driveway	44



#77 2010 Building: Southern Building Entrance Utilities	46
#76 2010 Building: Western Building Sidewalk & Entrance	47
#75 2010 Building: Western Building Entrance Utilities	49
#74 2010 Building: Western Landscape Area	50
#73 2010 Building: Front Landscape Area	52
#72 2010 Building: Front Landscape Area	55
#71 Bus Drop-off: Pavement Conditions & Striping	57
#70 Outdoor Gathering Area	59
#69 Bus Drop-off: Pavement Conditions & Parking	64
#68 Bus Drop-off: Pavement Conditions & Striping	68
#67 1927 Building: West Basement Window Well	71
#66 1927 Building: Main Entrance	74
#65 1927 Building: Bicycle parking and Landscape areas	78
#64 Bus Drop-off: Pavement Conditions & Parking	80
#63 1927 Building: East Basement Window Well	84
#62 Southeastern Bus Drop-off: Sidewalks & Landscape areas	86
#61 1927 Building: Southeast Corner Modular walls, Sidewalks & Landscape areas	90
#60 1927 Building: Southeast Corner Modular wall	93
#59 1927 Building to Southeastern Parking Lot Connection	95
#58 1927 Building: East Existing Utilities	98
#57 1927 Building: East Existing Utilities	99
#56 1927 Building: East Exit Landing & Sidewalk	100
#55 Eastern Courtyard: Seating Patio	102
#54 Eastern Courtyard: Existing building connections, Drainage & Landscaping	104
#53 Eastern Courtyard: Existing Sidewalks, Drainage & Landscaping	106
#52 Eastern Courtyard: Existing Sidewalks, Drainage & Landscaping	109



#51 Eastern Courtyard: Existing Sidewalks, Landscaping walls, Drainage & Landscaping	112
#50 Eastern Courtyard: Drainage & Landscaping	117
#49 Eastern Courtyard: Drainage & Landscaping	120
#48 Gymnasium Southern Patio	123
#47 Gymnasium Northern Parking area and Access Ramp	127
#46 Gymnasium Northern face: Existing Downspouts and Building Landing	131
#45 Northeastern Parking Area: Drop Inlet	135
#44 Northeastern Parking Area: Existing pavement	137
#43 Storage Building Northeastern Parking Area: Building, Existing pavement and C&G	138
#42 Tennis Courts	140
#41 Gymnasium Northeastern Parking area: Drop Inlet & Drainage Issues	147
#40 Gymnasium Northeastern Parking area: Large Boundary Trees	150
#39 Gymnasium Northeastern Parking area: Drop Inlet & Drainage Issues	152
#38 Gymnasium Northeastern Parking area: Drainage Conditions and Existing pavement	154
#37 East Access Drive: Low point drainage issue & Damaged fencing	157
#36 Gymnasium Northeast Stairs	159
#35 East Access Drive: Drop Inlet, Existing pavement, C&G and Retaining wall	161
#34 East Access Drive: Existing pavement, C&G and Retaining wall	165
#33 East Access Drive: Existing pavement, C&G and Retaining wall	169
#32 East Access Drive: Existing pavement, C&G and Retaining wall	172
#31 East Access Drive: Drop Inlet	176
#30 Southern Parking Lot: Large Boundary Tree	178
#29 Southern Parking Lot: Existing pavement and C&G	179
#28 Southern Parking Lot: Large Ash Tree	183
#27 Southern Parking Lot: Gymnasium Stairs & Sidewalk	184
#26 Southern Parking Lot: Pedestrian & Stair Connection	189

DCSD - Druid Hills HS Modernization



#25 Southern Parking Lot: Large Oak & Ash Tree	. 192
#24 Southern Parking Lot: Existing pavement and C&G	. 193
#23 Southern Parking Lot: Existing pavement and Existing Retaining Wall	. 196
#22 Southern Parking Lot: Existing pavement and Sewer manhole	. 199
#21 Southern Parking Lot: Existing Light Poles	. 202
#20 Southern Parking Lot: Existing pavement and C&G	. 203
#19 Southern Parking Lot: Existing pavement and Existing Retaining Wall	. 206
#18 Southern Parking Lot: Dumpsters	. 208
#17 Southern Parking Lot: Existing pavement and C&G	. 210
#16 Southern Parking Lot: Existing Storm Structure	. 212
#15 Southern Parking Lot: Existing pavement and C&G	. 214
#14 Southern Parking Lot: Boundary Tree	. 217
#13 Southern Parking Lot: Large Boundary Tree	. 218
#12 Southern Parking Lot: Existing pavement and C&G	. 219
#11 Southern Parking Lot Entrance Drive: Existing Power Pole	. 222
#10 Southern Parking Lot Entrance Drive: Existing pavement	. 223
#9 Southern Parking Lot Entrance Drive: Existing pavement, Sidewalk, C&G and Utilities	. 225
#8 Southern Parking Lot Entrance Drive: Large Oak Tree	. 228
#7 Haygood Drive & North Decatur Drive Intersection	. 229
#6 Southern Parking Lot Exit Drive: Drop Inlet	. 230
#5 Southern Parking Lot Exit Drive: Existing pavement, Sidewalk, and C&G	. 232
#4 Southern Right-of-Way Parking: Existing Utilities	. 235
#3 Southern Right-of-Way Parking: Existing pavement, Sidewalk and C&G	238
#2 Entrance Drop-off Driveway: Existing Utilities	241
#1 Entrance Drop-off Driveway: Existing Pavement, Sidewalk and C&G	. 242



#95 Field to Central Courtyard Connection: Drainage & Sidewalks

Status

Created Open

Dec 5, 2023 10:10 AM clanman@eberly.net

Type

Last Updated Issue

Jan 29, 2024 11:45 AM

Description

Existing concrete sidewalks, stairs, & wall experiencing cracking and staining. Condition varies in areas ranging from good / fair / poor conditions.

Drainage throughout area not clearly defined. Stormwater route to structure / pipes unclear or does not drain.

Handrails do not appear to adhere to standard / code requirements.

Landscape areas slopes vary, relatively dense vegetative cover exists throughout. Minor erosion occurring in areas.

Photos

Sheet







20231120_115126_photo **Cody Lanman** Nov 20, 2023 11:51 AM



20231120_115058_photo **Cody Lanman** Nov 20, 2023 11:51 AM



#94 Field Parking Area: Pavement & Drainage

Status

Open

Туре

Issue

Description

Asphalt pavement and curb in gutter conditions experiencing cracking & settling, appear to be in fair / poor condition.

Striping is faded or missing in areas.

Inlet and structure appear to be full of trash and debris. Multiple pipes into structure not reflected on survey. Direction of drainage unclear.

Low point within pavement area, insufficient slope to adjacent storm structures. Resulting in accumulation of water, sediment and debris in area.

Photos

Created SI

Dec 5, 2023 10:10 AM clanman@eberly.net

Last Updated

Jan 28, 2024 10:55 PM

Sheet







20231120_115036_photo **Cody Lanman** Nov 20, 2023 11:50 AM



20231120_115020_photo **Cody Lanman** Nov 20, 2023 11:50 AM





20231120_114959_photo **Cody Lanman** Nov 20, 2023 11:50 AM



#93 Track & Field: Southeastern Drainage & Asphalt

Status Created

Open Dec 5, 2023 10:10 AM

clanman@eberly.net

Type

Issue Last Updated

Jan 28, 2024 10:53 PM

Description

Field and track grading varies and does not clearly drain to drop inlet. Areas appear to be lower than drop inlet rim.

Inlet grate and structure full of sediment & debris.

Portions of field are thin and in moderate condition. Track asphalt experiencing cracking and deviations in surface. Pavement appears to be in moderate to fair condition.

Photos

Sheet



DCSD - Druid Hills HS Modernization





20231120_114613_photo **Cody Lanman** Nov 20, 2023 11:46 AM



#92 Track & Field: Northeastern Drainage & Asphalt

Status

Created Open

Dec 5, 2023 10:10 AM

clanman@eberly.net

Type Issue

Last Updated

Jan 28, 2024 10:53 PM

Description


Field and track grading varies and does not clearly drain to drop inlet. Areas appear to be lower than drop inlet rim.

Inlet grate and structure full of sediment & debris.

Portions of field are thin and in moderate condition. Track asphalt experiencing cracking and deviations in surface. Pavement appears to be in moderate to fair condition.

Photos

Sheet







20231120_114511_photo **Cody Lanman** Nov 20, 2023 11:45 AM



20231120_114506_photo **Cody Lanman** Nov 20, 2023 11:45 AM





20231120_114500_photo **Cody Lanman** Nov 20, 2023 11:45 AM



#91 Track & Field: Northeastern Drainage & Asphalt

Status Created

Open Dec 5, 2023 10:10 AM

clanman@eberly.net

Type

Issue Last Updated

Jan 28, 2024 10:52 PM

Description


Minor erosion / washout occurring at property line

along railroad.

Track asphalt experiencing cracking and deviations in surface. Pavement appears to be in moderate to fair condition.

Photos

Sheet







20231120_114427_photo **Cody Lanman** Nov 20, 2023 11:44 AM



20231120_114359_photo **Cody Lanman** Nov 20, 2023 11:44 AM



#90 Track & Field: Northwestern Drainage & Asphalt

Status

Created

Open

Dec 5, 2023 10:10 AM clanman@eberly.net

Type

Issue

Last Updated

Jan 28, 2024 10:51 PM

Description


Minor erosion / washout occurring at property line along railroad.

Field and track grading varies and does not clearly drain to drop inlet. Inlet grate and structure full of sediment & debris.

Portions of field are thin and in moderate condition. Track asphalt experiencing cracking and deviations in surface. Pavement appears to be in moderate to fair condition.

Photos

Sheet







20231120_113953_photo **Cody Lanman** Nov 20, 2023 11:39 AM



20231120_113942_photo **Cody Lanman** Nov 20, 2023 11:39 AM





20231120_113843_photo **Cody Lanman** Nov 20, 2023 11:39 AM



#89 Track & Field: Southwestern Drainage & Asphalt

Status Open **Created** Dec 5, 2023 10:10 AM

clanman@eberly.net

Type Issue

Last Updated

Jan 28, 2024 10:51 PM

Description


Field and track grading varies and does not clearly drain to drop inlet. Areas appear to be lower than drop inlet rim.

Inlet grate and structure full of sediment & debris.

Portions of field are thin and in moderate condition. Track asphalt experiencing cracking and deviations in surface. Pavement appears to be in moderate to fair condition.

Photos


Sheet







20231120_113641_photo Cody Lanman Nov 20, 2023 11:36 AM



20231120_113635_photo **Cody Lanman** Nov 20, 2023 11:36 AM

DCSD - Druid Hills HS Modernization





20231120_113629_photo **Cody Lanman** Nov 20, 2023 11:36 AM



#88 Softball Field: Western Drainage

Status

Open

Type Issue

Description

Area surrounding softball field full of miscellaneous debris. Grading & drainage not clearly defined and grading to storm infrastructure unclear.

Created


Dec 5, 2023 10:10 AM clanman@eberly.net

Last Updated

Jan 28, 2024 10:52 PM

Sheet

1



Photos



20231120_113534_photo **Cody Lanman** Nov 20, 2023 11:35 AM



#87 1953 Building Eastern Stair Connection

Status

Open

Type Issue

Description

Existing sidewalk and stairs experiencing cracking and appear to be in moderate / poor condition. Stair handrails do not appear to adhere to standard configuration.

Photos


Created

Dec 5, 2023 10:10 AM clanman@eberly.net

Last Updated

Jan 28, 2024 10:46 PM

Sheet







20231120_113452_photo **Cody Lanman** Nov 20, 2023 11:34 AM



#86 1961 Lift Station

Status

Open

Type Issue

Description

1961 Lift Station Building, pump & well. System appears to be leaking & in poor condition (Owner notified day of regarding conditions).

Created


Dec 5, 2023 10:10 AM clanman@eberly.net

Last Updated

Jan 28, 2024 10:44 PM

Sheet

1



Photos



20231120_113058_photo **Cody Lanman** Nov 20, 2023 11:31 AM



20231120_113005_photo **Cody Lanman** Nov 20, 2023 11:30 AM





20231120_112943_photo **Cody Lanman** Nov 20, 2023 11:29 AM



#85 Field Area Existing Stone Wall

Status

Open

Type Issue

Description

Existing stone wall appears in relatively good / fair condition. Significantly overgrown with vines & vegetation in areas.

Drainage behind & at top of wall not clearly defined to divert water around structure.

Fencing along top of wall in poor condition.

Miscellaneous equipment and concrete pads exist throughout area.

Photos


Created

Dec 5, 2023 10:09 AM clanman@eberly.net

Last Updated

Jan 28, 2024 10:35 PM

Sheet







20231120_112928_photo Cody Lanman Nov 20, 2023 11:29 AM



20231120_112919_photo **Cody Lanman** Nov 20, 2023 11:29 AM



#84 Western Courtyard to Lower Building Access: Sidewalk & Drainage

Status

Created

Open

Dec 5, 2023 10:09 AM clanman@eberly.net

Type

Issue

Last Updated

Jan 28, 2024 10:31 PM

Description

Existing concrete sidewalks, stairs, & wall experiencing cracking and staining.
Condition varies in areas ranging from good / fair / poor conditions.

No handrails present.


Large Oak Tree (+/- 42"). (Tree species indicated are as reflected on 2007 Survey)

Existing downspout boot connections in fair / poor conditions.

Landscape areas vegetation is sparse in areas and grading does not consistently slope away from buildings / features.

Photos

Sheet







20231120_112745_photo **Cody Lanman** Nov 20, 2023 11:27 AM



20231120_112732_photo **Cody Lanman** Nov 20, 2023 11:27 AM





20231120_112725_photo **Cody Lanman** Nov 20, 2023 11:27 AM



#83 Central Campus Pedestrian Connections & Wooded Area

Status Open Created

Dec 5, 2023 10:09 AM

clanman@eberly.net

Type Issue

Last Updated

Jan 28, 2024 10:29 PM

SI)

Sheet

2

Description

Existing concrete sidewalks, ramps, and walls experiencing cracking and staining. Condition varies in areas ranging from good / fair / poor conditions.

Existing canopy downspouts / boot connections in fair / poor conditions.

Landscape areas slopes vary, relatively dense vegetative cover exists throughout. Minor erosion occurring in areas.

Photos





20231120_111430_photo **Cody Lanman** Nov 20, 2023 11:14 AM



20231120_111423_photo **Cody Lanman** Nov 20, 2023 11:14 AM





20231120_111403_photo **Cody Lanman** Nov 20, 2023 11:14 AM



#82 Western Courtyard: Drainage & Landscape

Status Created

Open Dec 5, 2023 10:09 AM

clanman@eberly.net

Type

ISSUE Last Updated

Jan 28, 2024 10:27 PM

Description

Existing concrete sidewalks, curbs and walls experiencing cracking and staining.

Condition varies in areas ranging from good / fair / poor conditions.


Connecting landings at sidewalk connections appear to be nearing / exceeding allowable slopes.

Existing downspout boot connections in fair / poor conditions.

Landscape areas vegetation grading does not consistently slope away from buildings / features.
Drainage paths not clearly defined.

Photos

Sheet







20231120_111323_photo **Cody Lanman** Nov 20, 2023 11:13 AM



20231120_111316_photo **Cody Lanman** Nov 20, 2023 11:13 AM



#81 Central Courtyard: Sidewalks & Drainage

Status Created

Open Dec 5, 2023 10:09 AM

clanman@eberly.net

Type

ISSUE Last Updated

Jan 28, 2024 10:25 PM

Description

Existing concrete sidewalks, ramps, and walls experiencing cracking and staining. Condition varies in areas ranging from good / fair / poor conditions.


Connecting landings at sidewalk connections appear to be nearing / exceeding allowable slopes.

Existing canopy downspouts / boot connections in fair / poor conditions.

Landscape areas vegetation is sparse in areas and grading does not consistently slope away from buildings / features.

Photos

Sheet







20231120_111130_photo **Cody Lanman** Nov 20, 2023 11:11 AM



20231120_111123_photo **Cody Lanman** Nov 20, 2023 11:11 AM



#80 Central Courtyard: Drainage & Landscaping

Status

Open

Type Issue

Description

Area drain covered with vegetation and debris. Structure appears full of debris and not properly draining.

Existing downspout boot connections in fair / poor conditions.

Landscape areas vegetation grading does not consistently slope away from buildings / features.
Drainage paths not clearly defined.

Photos


Created

Dec 5, 2023 10:09 AM clanman@eberly.net

Last Updated

Jan 28, 2024 10:24 PM

Sheet







20231120_110931_photo **Cody Lanman** Nov 20, 2023 11:09 AM



20231120_110924_photo **Cody Lanman** Nov 20, 2023 11:09 AM



#79 Sidewalk Connection to Central Courtyard

Status Created

Open Dec 5, 2023 10:09 AM

clanman@eberly.net

Type

ISSUE Last Updated

Jan 28, 2024 10:22 PM

Description

Existing concrete sidewalks & walls experiencing cracking and staining.
Condition varies in areas ranging from good / fair / poor conditions.

Connecting landings at sidewalk connections appear to be nearing / exceeding allowable slopes.


Landscape areas vegetation is sparse in areas and grading does not consistently slope away from buildings / features.

Window well full of trash and debris. No drainage infrastructure present within area.

Downspout connections appear in fair condition.

Photos

Sheet







20231120_110826_photo **Cody Lanman** Nov 20, 2023 11:08 AM



20231120_110820_photo **Cody Lanman** Nov 20, 2023 11:08 AM



#78 Bus Drop-off: Exit Driveway

Status Created

Open Dec 5, 2023 10:09 AM

clanman@eberly.net

Type

ISSUE Last Updated

Jan 28, 2024 10:20 PM

Description

Asphalt driveway and curb in gutter conditions experiencing some cracking & settling, appear to be in good / fair condition.


Sidewalks experiencing some cracking and chipping, appear in fair condition.

Driveway configuration and connection to right-of-way not does not appear to adhere to standard recommendations and does not appear to meet code dimensions.

ADA curb ramps and crosswalk do not appear to be compliant, and crosswalk striping faded.

Photos

Sheet







20231120_110650_photo **Cody Lanman** Nov 20, 2023 11:06 AM



#77 2010 Building: Southern Building Entrance Utilities

Status

Open

Туре

Issue

Description

Documentation of existing utility infrastructure. Existing fire meter, DDC, BFP, PIV & FDC. Size not indicated on survey or as-builts.

Created


Dec 5, 2023 10:09 AM clanman@eberly.net

Last Updated

Jan 28, 2024 10:18 PM

Sheet

2



Photos



20231120_110639_photo **Cody Lanman** Nov 20, 2023 11:06 AM



#76 2010 Building: Western Building Sidewalk & Entrance

StatusCreatedSheetOpenDec 5, 2023 10:09 AM2

clanman@eberly.net

Issue Last Updated

Jan 28, 2024 10:16 PM

Description

Type

Landscape areas vegetation is sparse in areas and grading does not consistently slope away from buildings / features.

Existing downspouts missing energy dissipation. Washout and erosion occurring in areas.

Photos





20231120_110247_photo **Cody Lanman** Nov 20, 2023 11:02 AM



#75 2010 Building: Western Building Entrance Utilities

Status

Open

Type Issue

Description

Documentation of existing utility infrastructure. Existing water meter and BFP, size not indicated on survey or as-builts.

Created


Dec 5, 2023 10:09 AM clanman@eberly.net

Last Updated

Jan 28, 2024 10:17 PM

Sheet

2



Photos



20231120_110156_photo **Cody Lanman** Nov 20, 2023 11:01 AM



#74 2010 Building: Western Landscape Area

Status Created

Open Dec 5, 2023 10:09 AM

clanman@eberly.net

Type

Issue Last Updated

Jan 28, 2024 10:13 PM


Description

Landscape areas vegetation is sparse in areas and grading does not consistently slope away from buildings / features.

Overflow drain does not have splash guard or energy dissipation.

Photos

Sheet







20231120_110139_photo **Cody Lanman** Nov 20, 2023 11:01 AM



#73 2010 Building: Front Landscape Area

Status

Created

Open

Dec 5, 2023 10:09 AM clanman@eberly.net

Type

Issue

Last Updated

Jan 28, 2024 10:11 PM

Description


Landscape area grading not clearly defined. Grades do not slope to area drains and outlet point not apparent.

Weir or restrictive structure installed on stone wall. Survey / Civil As-builts does not clearly indicate purpose of pate.

Sidewalks experiencing minor cracking but appear in generally good condition.

Photos

Sheet







20231120_110109_photo **Cody Lanman** Nov 20, 2023 11:01 AM



20231120_110046_photo **Cody Lanman** Nov 20, 2023 11:00 AM





20231120_110004_photo **Cody Lanman** Nov 20, 2023 11:00 AM



#72 2010 Building: Front Landscape Area

Status

Dec 5, 2023 10:08 AM

Created

clanman@eberly.net

Туре

Open

Issue Last Updated

Jan 28, 2024 10:03 PM


Description

Landscape area grading not clearly defined. Grades to not slope to area drains and outlet point not apparent.

Downspout disconnects & energy dissipation allowing washout. Vegetation is sparse in areas.

Photos

Sheet







20231120_105818_photo **Cody Lanman** Nov 20, 2023 10:58 AM



20231120_105810_photo **Cody Lanman** Nov 20, 2023 10:58 AM



#71 Bus Drop-off: Pavement Conditions & Striping

Status Created

Open Dec 5, 2023 10:08 AM

clanman@eberly.net

Type

Issue Last Updated

Jan 28, 2024 10:00 PM

Description


Asphalt pavement and curb in gutter conditions experiencing some cracking & settling. Conditions vary ranging from good, fair and poor in areas.

Parking and crosswalk striping very faded.

Sidewalks experiencing cracking and chipping, appear in good / fair condition.

Photos


Sheet







20231120_104548_photo **Cody Lanman** Nov 20, 2023 10:45 AM



20231120_104540_photo **Cody Lanman** Nov 20, 2023 10:45 AM



#70 Outdoor Gathering Area

Status

Open

Туре

Issue

Description

Sidewalks experiencing cracking and chipping, appear in good / fair condition.

Pedestrian access in area limited. Grading & drainage within area inconsistent and does not clearly divert runoff within area.

Photos


Created

Dec 5, 2023 10:08 AM clanman@eberly.net

Last Updated

Jan 28, 2024 10:00 PM

Sheet







20231120_104440_photo Cody Lanman Nov 20, 2023 10:44 AM




20231120_104432_photo **Cody Lanman** Nov 20, 2023 10:44 AM





20231120_104426_photo **Cody Lanman** Nov 20, 2023 10:44 AM



20231120_104421_photo **Cody Lanman**Nov 20, 2023 10:44 AM





20231120_104408_photo **Cody Lanman** Nov 20, 2023 10:44 AM



20231120_104402_photo **Cody Lanman** Nov 20, 2023 10:44 AM





20231120_104354_photo **Cody Lanman** Nov 20, 2023 10:43 AM



#69 Bus Drop-off: Pavement Conditions & Parking

Status Created

Open Dec 5, 2023 10:08 AM

clanman@eberly.net

Type

Issue Last Updated

Jan 28, 2024 9:58 PM

Description

Asphalt pavement and curb in gutter conditions experiencing some cracking & settling. Conditions vary ranging from good, fair and poor in areas.


Parking and crosswalk striping very faded.

Sidewalks experiencing cracking and chipping, appear in good / fair condition.

ADA parking area faded and appears to be approaching / exceeding allowable slopes. Ramp does not appear to be client.

Photos

Sheet







20231120_104336_photo **Cody Lanman** Nov 20, 2023 10:43 AM



20231120_104329_photo **Cody Lanman** Nov 20, 2023 10:43 AM





20231120_104322_photo **Cody Lanman** Nov 20, 2023 10:43 AM



20231120_104313_photo **Cody Lanman** Nov 20, 2023 10:43 AM





20231120_104306_photo **Cody Lanman** Nov 20, 2023 10:43 AM



#68 Bus Drop-off: Pavement Conditions & Striping

Status Created

Open Dec 5, 2023 10:08 AM

clanman@eberly.net

Type

Issue Last Updated

Jan 28, 2024 9:57 PM


Description

Asphalt pavement, Speed bumps and curb & gutter conditions experiencing some cracking & settling. Conditions vary ranging from good, fair and poor in areas.

Paint & striping very faded.

Photos

Sheet







20231120_104252_photo **Cody Lanman** Nov 20, 2023 10:42 AM



20231120_104232_photo **Cody Lanman** Nov 20, 2023 10:42 AM





20231120_104226_photo **Cody Lanman** Nov 20, 2023 10:42 AM



#67 1927 Building: West Basement Window Well

Status Created

Open Dec 5, 2023 10:08 AM

clanman@eberly.net

Type

Issue Last Updated

Jan 28, 2024 9:55 PM

Description


Window well full of trash and debris. No drainage infrastructure present within

area.

Downspout connections appear in fair condition.

Photos

Sheet







20231120_104156_photo **Cody Lanman** Nov 20, 2023 10:41 AM



20231120_104148_photo **Cody Lanman** Nov 20, 2023 10:41 AM





20231120_104140_photo **Cody Lanman** Nov 20, 2023 10:41 AM



#66 1927 Building: Main Entrance

Status Created

Open Dec 5, 2023 10:07 AM

clanman@eberly.net

Type

Issue Last Updated

Jan 28, 2024 9:55 PM

Description

Sidewalks experiencing minor cracking and chipping, appear in generally good condition.

Main entrance stairs and railing appears in generally good condition.

No ADA connection exists at building main entrance.

Photos

Sheet







20231120_104059_photo **Cody Lanman** Nov 20, 2023 10:41 AM



20231120_104049_photo **Cody Lanman** Nov 20, 2023 10:40 AM





20231120_104026_photo **Cody Lanman** Nov 20, 2023 10:40 AM



20231120_104020_photo **Cody Lanman** Nov 20, 2023 10:40 AM





20231120_104011_photo **Cody Lanman** Nov 20, 2023 10:40 AM



#65 1927 Building: Bicycle parking and Landscape areas

StatusCreatedSheetOpenDec 5, 2023 10:07 AM2

clanman@eberly.net

Issue Last Updated

Jan 28, 2024 9:53 PM

Description


Type

Documentation of existing infrastructure and bicycle parking.

Landscape areas vegetation is sparse in areas and grading does not consistently slope towards storm infrastructure.

Transitions to landscape areas in ranging conditions & not clearly defined causing mulch & vegetative debris to spill onto sidewalks.

Photos







20231120_103959_photo **Cody Lanman** Nov 20, 2023 10:40 AM



#64 Bus Drop-off: Pavement Conditions & Parking

Status Created

Open Dec 5, 2023 10:07 AM

clanman@eberly.net

Туре

Issue Last Updated

Jan 28, 2024 9:51 PM

Description

Asphalt pavement and curb in gutter conditions experiencing some cracking & settling. Conditions vary ranging from good, fair and poor in areas.

Parking and crosswalk striping very faded.

Sidewalks experiencing significant cracking and chipping, appear in fair condition.

ADA parking area faded and appears to be approaching / exceeding allowable slopes.

Photos

Sheet







20231120_103943_photo Cody Lanman Nov 20, 2023 10:39 AM



20231120_103933_photo **Cody Lanman** Nov 20, 2023 10:39 AM





20231120_103912_photo **Cody Lanman** Nov 20, 2023 10:39 AM



20231120_103901_photo **Cody Lanman** Nov 20, 2023 10:39 AM





20231120_103854_photo **Cody Lanman** Nov 20, 2023 10:38 AM



#63 1927 Building: East Basement Window Well

Status Created

Open Dec 5, 2023 10:07 AM

clanman@eberly.net

Type

Issue Last Updated

Jan 28, 2024 9:55 PM

Description

Window well full of trash and debris. No drainage infrastructure present within

area.

Downspout connections appear in fair condition.

Photos

Sheet







20231120_103254_photo Cody Lanman Nov 20, 2023 10:32 AM



20231120_103236_photo **Cody Lanman** Nov 20, 2023 10:32 AM



#62 Southeastern Bus Drop-off: Sidewalks & Landscape areas

Created

Last Updated

Dec 5, 2023 10:07 AM

Jan 28, 2024 9:53 PM

clanman@eberly.net

Status

Open

Туре

Issue

Description

Asphalt pavement and curb in gutter conditions experiencing some cracking & settling, appear to be in generally good condition.

Parking and crosswalk striping very faded.

Sidewalks experiencing significant cracking and chipping, appear in fair condition.

Landscape areas vegetation is sparse in areas and grading does not consistently slope towards storm infrastructure.

Transitions to landscape areas in ranging conditions & not clearly defined causing mulch & vegetative debris to spill onto sidewalks.

Photos

Sheet







20231120_103144_photo **Cody Lanman** Nov 20, 2023 10:31 AM



20231120_103137_photo **Cody Lanman** Nov 20, 2023 10:31 AM





20231120_103125_photo **Cody Lanman** Nov 20, 2023 10:31 AM



20231120_103116_photo **Cody Lanman** Nov 20, 2023 10:31 AM





20231120_103111_photo **Cody Lanman** Nov 20, 2023 10:31 AM



#61 1927 Building: Southeast Corner Modular walls, Sidewalks & Landscape areas

Status Open Created

Dec 5, 2023 10:07 AM clanman@eberly.net

Type

Issue Last Updated

Jan 28, 2024 9:40 PM

Description

Modular wall appears damaged or loose in areas. Staining & discoloration indicates potential drainage issue.

Landscape areas vegetation is sparse in areas and grading does not consistently slope away from buildings / features.

Existing concrete sidewalks experiencing cracking and staining. Condition varies in areas ranging from good / fair conditions.

Photos

Sheet







20231120_103050_photo **Cody Lanman** Nov 20, 2023 10:30 AM



20231120_103027_photo **Cody Lanman** Nov 20, 2023 10:30 AM





20231120_103018_photo **Cody Lanman** Nov 20, 2023 10:30 AM



#60 1927 Building: Southeast Corner Modular wall

Status

Created Open

Dec 5, 2023 10:07 AM clanman@eberly.net

Type

Last Updated Issue

Jan 28, 2024 9:38 PM

Description

Modular wall appears damaged or loose in areas. Staining & discoloration indicates potential drainage issue.

Landscape areas vegetation is sparse in areas and grading does not consistently slope away from buildings / features.

Existing downspout boot connections in fair / poor conditions.

Photos

Sheet







20231120_102947_photo **Cody Lanman** Nov 20, 2023 10:29 AM



20231120_102934_photo **Cody Lanman** Nov 20, 2023 10:29 AM



#59 1927 Building to Southeastern Parking Lot Connection

Status

Created

Open Dec 5, 2023 10:07 AM

clanman@eberly.net

Type

Issue

Last Updated

Jan 28, 2024 9:36 PM

Description

Existing sidewalk and stairs experiencing cracking and appear to be in fair condition. Stair handrails do not appear to adhere to standard configuration.

Fencing appears to be damaged in areas. Wooden slope edging and landscape beds appear to be in poor condition. Erosion and washout occurring within areas.

Photos

Sheet







20231120_102905_photo Cody Lanman Nov 20, 2023 10:29 AM



20231120_102858_photo **Cody Lanman** Nov 20, 2023 10:29 AM





20231120_102849_photo **Cody Lanman** Nov 20, 2023 10:28 AM



#58 1927 Building: East Existing Utilities

Status

Open

Type Issue

Description

Documentation of existing utility conditions. Existing sanitary sewer manhole.

Created


Dec 5, 2023 10:07 AM clanman@eberly.net

Last Updated

Jan 28, 2024 9:33 PM

Sheet

2



Photos



20231120_102829_photo **Cody Lanman** Nov 20, 2023 10:28 AM



#57 1927 Building: East Existing Utilities

Status

Open

Туре

Issue

Description

Documentation of existing utility conditions. Appears to be sanitary sewer cleanout.

Created


Dec 5, 2023 10:07 AM clanman@eberly.net

Last Updated

Jan 28, 2024 9:32 PM

Sheet

2



Photos



20231120_102816_photo **Cody Lanman** Nov 20, 2023 10:28 AM



#56 1927 Building: East Exit Landing & Sidewalk

Status Created

Open Dec 5, 2023 10:07 AM

clanman@eberly.net

Type

Issue Last Updated

Jan 28, 2024 9:31 PM

Description

Existing concrete sidewalks experiencing cracking and staining. Condition generally in good condition.

Connecting landings to building stairs appear to be nearing / exceeding allowable slopes.

Photos

Sheet







20231120_102804_photo **Cody Lanman** Nov 20, 2023 10:28 AM



20231120_102756_photo **Cody Lanman** Nov 20, 2023 10:27 AM



#55 Eastern Courtyard: Seating Patio

Status Created

Open Dec 5, 2023 10:07 AM

clanman@eberly.net

Type

Issue Last Updated

Jan 28, 2024 9:28 PM

Description

Documenting existing courtyard patio area. No drainage apparent within area. Landscape areas vegetation is sparse in areas and grading does not consistently slope away from buildings / features.

Photos

Sheet







20231120_102726_photo Cody Lanman Nov 20, 2023 10:27 AM



20231120_102718_photo **Cody Lanman** Nov 20, 2023 10:27 AM



#54 Eastern Courtyard: Existing building connections, Drainage & Landscaping

Status Open Created
Dec 5, 2023 10:06 AM clanman@eberly.net

Туре

Issue

Last Updated

Jan 28, 2024 9:23 PM

Description

Existing concrete sidewalks experiencing cracking and staining. Condition varies in areas ranging from good / fair / poor conditions.


Connecting landings to building stairs appear to be nearing / exceeding allowable slopes.

Existing downspout boot connections in fair / poor conditions.

Landscape areas vegetation is sparse in areas and grading does not consistently slope away from buildings / features.

Photos

Sheet







20231120_102706_photo **Cody Lanman** Nov 20, 2023 10:27 AM



20231120_102654_photo **Cody Lanman** Nov 20, 2023 10:26 AM



#53 Eastern Courtyard: Existing Sidewalks, Drainage & Landscaping

Status Open Created
Dec 5, 2023 10:06 AM clanman@eberly.net

Туре

Issue

Last Updated

Jan 28, 2024 9:39 PM

Description

Existing concrete sidewalks experiencing cracking and staining. Condition varies in areas ranging from good / fair / poor conditions.

Connecting landings at sidewalk to building appear to be nearing / exceeding allowable slopes.

Existing downspout boot connections in fair / poor conditions.

Landscape areas vegetation is sparse in areas and grading does not consistently slope away from buildings / features.

Photos

Sheet







20231120_102632_photo **Cody Lanman** Nov 20, 2023 10:26 AM



20231120_102622_photo **Cody Lanman** Nov 20, 2023 10:26 AM





20231120_102613_photo **Cody Lanman** Nov 20, 2023 10:26 AM



#52 Eastern Courtyard: Existing Sidewalks, Drainage & Landscaping

Status

Open

Type

Issue

Created

Dec 5, 2023 10:06 AM clanman@eberly.net

Jan 28, 2024 9:21 PM

Last Updated

Description

Existing concrete sidewalks experiencing cracking and staining. Condition varies in areas ranging from good / fair / poor conditions.


Connecting landings at sidewalk to building appear to be nearing / exceeding allowable slopes.

Existing downspout boot connections in fair / poor conditions.

Landscape areas vegetation is sparse in areas and grading does not consistently slope away from buildings / features.

Photos

Sheet







20231120_102553_photo **Cody Lanman** Nov 20, 2023 10:25 AM



20231120_102545_photo Cody Lanman Nov 20, 2023 10:25 AM





20231120_102538_photo **Cody Lanman** Nov 20, 2023 10:25 AM



#51 Eastern Courtyard: Existing Sidewalks, Landscaping walls, Drainage & Landscaping

Status

Created

Open

Dec 5, 2023 10:06 AM clanman@eberly.net

Type

Issue

Last Updated

Jan 28, 2024 9:19 PM

Description

Existing concrete sidewalks & landscape wall experiencing cracking and staining. Condition varies in areas ranging from good / fair / poor conditions.


Connecting landings at sidewalk connections appear to be nearing / exceeding allowable slopes.

Existing downspout boot connections in fair / poor conditions.

Landscape areas vegetation is sparse in areas and grading does not consistently slope away from buildings / features.

Photos

Sheet







20231120_095855_photo Cody Lanman Nov 20, 2023 9:58 AM



20231120_095849_photo Cody Lanman Nov 20, 2023 9:58 AM





20231120_095841_photo **Cody Lanman** Nov 20, 2023 9:58 AM



20231120_095833_photo **Cody Lanman** Nov 20, 2023 9:58 AM





20231120_095822_photo **Cody Lanman** Nov 20, 2023 9:58 AM



20231120_095815_photo Cody Lanman Nov 20, 2023 9:58 AM





20231120_095808_photo **Cody Lanman** Nov 20, 2023 9:58 AM



#50 Eastern Courtyard: Drainage & Landscaping

Status

Open

Type Issue

Description

Area drain covered with vegetation and debris. Structure appears full of debris and not properly draining.

Existing downspout boot connections in fair / poor conditions.

Landscape areas vegetation is sparse in areas and grading does not consistently slope away from buildings / features.

Photos

Created

Dec 5, 2023 10:06 AM clanman@eberly.net

Last Updated

Jan 28, 2024 10:23 PM

Sheet







20231120_095729_photo Cody Lanman Nov 20, 2023 9:57 AM



20231120_095723_photo **Cody Lanman** Nov 20, 2023 9:57 AM





20231120_095716_photo **Cody Lanman** Nov 20, 2023 9:57 AM



#49 Eastern Courtyard: Drainage & Landscaping

Status Created

Open Dec 5, 2023 10:06 AM

clanman@eberly.net

Type

Issue Last Updated

Jan 28, 2024 10:24 PM

Description


Existing downspout boot connections in fair / poor

conditions.

Landscape areas vegetation is sparse in areas and grading does not consistently slope away from buildings / features.

Photos

Sheet







20231120_095704_photo **Cody Lanman** Nov 20, 2023 9:57 AM



20231120_095654_photo Cody Lanman Nov 20, 2023 9:56 AM

DCSD - Druid Hills HS Modernization

1798 Haygood Drive Northeast, Atlanta, Georgia





20231120_095645_photo **Cody Lanman** Nov 20, 2023 9:56 AM



#48 Gymnasium Southern Patio

Status Created

Open Dec 5, 2023 10:06 AM

clanman@eberly.net

Last Updated

Type Issue

Jan 28, 2024 9:07 PM


Description

Gymnasium southern patio conditions. Concrete experiencing staining and minor cracking, but appears in generally good condition.

Retaining wall experiencing cracking and handrails in poor condition, may not adhere to code requirements.

Photos

Sheet







20231120_095624_photo **Cody Lanman** Nov 20, 2023 9:56 AM



20231120_095617_photo **Cody Lanman** Nov 20, 2023 9:56 AM





20231120_095607_photo **Cody Lanman** Nov 20, 2023 9:56 AM



20231120_095558_photo Cody Lanman Nov 20, 2023 9:56 AM





20231120_095550_photo **Cody Lanman** Nov 20, 2023 9:55 AM



#47 Gymnasium Northern Parking area and Access Ramp

Status Created

Open Dec 5, 2023 9:02 AM

clanman@eberly.net

Type

Issue Last Updated

Jan 28, 2024 9:04 PM


Description

Asphalt pavement conditions experiencing cracking & settling, appear to be in fair / poor condition.

Existing ramp chipped / damaged in areas.

Photos

Sheet







20231120_095431_photo **Cody Lanman** Nov 20, 2023 9:54 AM



20231120_095412_photo **Cody Lanman** Nov 20, 2023 9:54 AM





20231120_095400_photo **Cody Lanman** Nov 20, 2023 9:54 AM



20231120_095350_photo **Cody Lanman** Nov 20, 2023 9:53 AM





20231120_095344_photo **Cody Lanman** Nov 20, 2023 9:53 AM



#46 Gymnasium Northern face: Existing Downspouts and Building Landing

Status Open Created
Dec 5, 2023 9:02 AM clanman@eberly.net

Type

Issue

Last Updated

Jan 28, 2024 9:02 PM

Description


Existing stairs and handrails to gymnasium are damaged & chipped.

Documentation of existing downspout locations, several boot connections appear to be missing and in poor condition.

Asphalt pavement cracking & settling, appear to be in fair / poor condition.

Photos

Sheet







20231120_095332_photo **Cody Lanman** Nov 20, 2023 9:53 AM



20231120_095323_photo **Cody Lanman** Nov 20, 2023 9:53 AM






20231120_095316_photo **Cody Lanman** Nov 20, 2023 9:53 AM



20231120_095310_photo **Cody Lanman** Nov 20, 2023 9:53 AM





20231120_095303_photo **Cody Lanman** Nov 20, 2023 9:53 AM



#45 Northeastern Parking Area: Drop Inlet

Status Created

Open Dec 5, 2023 9:02 AM

clanman@eberly.net

Type

Issue Last Updated

Jan 28, 2024 8:58 PM


Description

Pavement surrounding drop inlet damaged and is not flush with grate and cover.

Inlet not aligned with drainage pattern. Inlet and structure appear to be full of trash and debris.

Photos

Sheet







20231120_095229_photo **Cody Lanman** Nov 20, 2023 9:52 AM



20231120_095215_photo **Cody Lanman** Nov 20, 2023 9:52 AM



#44 Northeastern Parking Area: Existing pavement

Status

Open

Type Issue

Description

Asphalt pavement conditions experiencing cracking & settling, appear to be in fair / poor condition.

Created


Dec 5, 2023 9:02 AM clanman@eberly.net

Last Updated

Jan 28, 2024 8:58 PM

Sheet

2



Photos



20231120_095205_photo **Cody Lanman** Nov 20, 2023 9:52 AM



20231120_095157_photo **Cody Lanman** Nov 20, 2023 9:51 AM



#43 Storage Building Northeastern Parking Area: Building, Existing pavement and C&G

Status

Open

Dec 5, 2023 9:02 AM clanman@eberly.net

Type

Issue

Last Updated

Created

Jan 28, 2024 8:55 PM


Description

Documentation of existing storage building conditions.

Asphalt pavement and curb in gutter conditions experiencing cracking & settling, appear to be in fair / poor condition.

Photos

Sheet







20231120_095145_photo **Cody Lanman** Nov 20, 2023 9:51 AM



20231120_095133_photo **Cody Lanman** Nov 20, 2023 9:51 AM



#42 Tennis Courts

Status

Open

Type Issue

Description

Tennis Court gates and fencing damaged / warped in areas. Court surface experiencing significant staining and cracking throughout surface.

Created


Dec 5, 2023 9:01 AM clanman@eberly.net

Last Updated

Jan 28, 2024 7:45 PM

Sheet

2



Photos



20231120_095111_photo **Cody Lanman** Nov 20, 2023 9:51 AM



20231120_095105_photo **Cody Lanman** Nov 20, 2023 9:51 AM









20231120_095030_photo **Cody Lanman** Nov 20, 2023 9:50 AM





20231120_095017_photo **Cody Lanman** Nov 20, 2023 9:50 AM



20231120_095002_photo **Cody Lanman** Nov 20, 2023 9:50 AM





20231120_094954_photo **Cody Lanman** Nov 20, 2023 9:49 AM



20231120_094924_photo **Cody Lanman** Nov 20, 2023 9:49 AM





20231120_094914_photo **Cody Lanman** Nov 20, 2023 9:49 AM



20231120_094907_photo **Cody Lanman** Nov 20, 2023 9:49 AM





20231120_094852_photo **Cody Lanman** Nov 20, 2023 9:48 AM



20231120_094835_photo **Cody Lanman** Nov 20, 2023 9:48 AM

DCSD - Druid Hills HS Modernization

1798 Haygood Drive Northeast, Atlanta, Georgia





20231120_094821_photo **Cody Lanman** Nov 20, 2023 9:48 AM



#41 Gymnasium Northeastern Parking area: Drop Inlet & Drainage Issues

Status

Open

Type Issue

Description

Inlet and structure appear to be full of trash and debris. Multiple pipes into structure not reflected on survey. Direction of drainage unclear.

Low point within pavement area, insufficient slope to adjacent storm structures. Resulting in accumulation of water, sediment and debris in area.

Photos

Sł


Dec 5, 2023 9:01 AM clanman@eberly.net

Last Updated

Created

Jan 28, 2024 7:43 PM

Sheet







20231120_115432_photo **Cody Lanman** Nov 20, 2023 11:54 AM




20231120_094744_photo **Cody Lanman** Nov 20, 2023 9:47 AM





20231120_094733_photo **Cody Lanman** Nov 20, 2023 9:47 AM



20231120_094721_photo **Cody Lanman** Nov 20, 2023 9:47 AM



#40 Gymnasium Northeastern Parking area: Large Boundary Trees

Status

Open

Type Issue

Description

Large Oak & Gum boundary trees. (Tree species indicated are as reflected on 2007 Survey) Created


Dec 5, 2023 9:01 AM clanman@eberly.net

Last Updated

Jan 28, 2024 7:40 PM

Sheet

2





20231120_094608_photo **Cody Lanman** Nov 20, 2023 9:46 AM



20231120_094601_photo **Cody Lanman** Nov 20, 2023 9:46 AM





20231120_094555_photo **Cody Lanman** Nov 20, 2023 9:45 AM



#39 Gymnasium Northeastern Parking area: Drop Inlet & Drainage Issues

Status

Open

Type Issue

Description

Pavement surrounding drop inlet damaged and is not flush with grate cover. Inlet and structure appear to be full of trash and debris.

Low point within pavement area, insufficient slope to adjacent storm structures. Resulting in accumulation of water, sediment and debris in area.

Photos


Created

Dec 5, 2023 9:01 AM clanman@eberly.net

Last Updated

Jan 28, 2024 7:38 PM

Sheet







20231120_094526_photo **Cody Lanman** Nov 20, 2023 9:45 AM



Cody LanmanNov 20, 2023 9:45 AM



#38 Gymnasium Northeastern Parking area: Drainage Conditions and Existing pavement

Status

Created

Open

Dec 5, 2023 9:01 AM clanman@eberly.net

Type

Issue

Last Updated

Jan 28, 2024 7:35 PM


Description

Documentation of existing downspout locations, several boot connections appear to be in poor condition.

Asphalt pavement cracking & settling, appear to be in fair / poor condition. Asphalt patch / repair locations appear in poor condition and experiencing pumping causing low points along top of retaining wall.

Photos

Sheet







20231120_094456_photo Cody Lanman Nov 20, 2023 9:44 AM



20231120_094449_photo **Cody Lanman** Nov 20, 2023 9:44 AM





20231120_094438_photo **Cody Lanman** Nov 20, 2023 9:44 AM



20231120_094430_photo **Cody Lanman** Nov 20, 2023 9:44 AM



#37 East Access Drive: Low point drainage issue & Damaged fencing

Status Created

Open Dec 5, 2023 9:01 AM

clanman@eberly.net

Type

Issue Last Updated

Jan 28, 2024 7:36 PM


Description

Low point along access drive and retaining wall, insufficient slope to adjacent storm structures. Resulting in accumulation of water, sediment and debris in area along top of retaining wall.

Existing fencing appears damaged in areas.

Photos

Sheet







20231120_094410_photo **Cody Lanman** Nov 20, 2023 9:44 AM



20231120_094402_photo Cody Lanman Nov 20, 2023 9:44 AM



#36 Gymnasium Northeast Stairs

Status

Open

Type Issue

Description

Existing stairs and handrails to gymnasium are damaged & chipped. Curbing around landing area appears higher than typical.

Created


Dec 5, 2023 9:01 AM clanman@eberly.net

Last Updated

Jan 28, 2024 9:01 PM

Sheet

2





20231120_094347_photo **Cody Lanman** Nov 20, 2023 9:43 AM



20231120_094340_photo Cody Lanman Nov 20, 2023 9:43 AM





20231120_094333_photo **Cody Lanman** Nov 20, 2023 9:43 AM



20231120_094326_photo **Cody Lanman** Nov 20, 2023 9:43 AM



#35 East Access Drive: Drop Inlet, Existing pavement, C&G and Retaining wall

Status Open Created
Dec 5, 2023 9:01 AM clanman@eberly.net

Туре

Issue

Last Updated

Jan 28, 2024 7:37 PM

Description

Pavement surrounding drop inlet damaged and is not flush with grate cover. Inlet and structure appear to be full of trash and debris.


Asphalt pavement and curb in gutter conditions experiencing cracking & settling, appear to be in fair / poor condition.

Driveway width does not appear to adhere to recommended layout or adhere to aerial apparatus fire code requirements.

Existing retaining wall and handrails are damaged. Note: Majority of access drive and wall are over property line, encroachment is identified on existing easement agreements with adjacent property owner.

Photos

Sheet







20231120_094257_photo Cody Lanman Nov 20, 2023 9:42 AM



20231120_094248_photo **Cody Lanman** Nov 20, 2023 9:42 AM





20231120_094240_photo **Cody Lanman** Nov 20, 2023 9:42 AM



20231120_094221_photo **Cody Lanman** Nov 20, 2023 9:42 AM





20231120_094203_photo **Cody Lanman** Nov 20, 2023 9:42 AM



#34 East Access Drive: Existing pavement, C&G and Retaining wall

Open

Status Created

Dec 5, 2023 9:00 AM clanman@eberly.net

Type

Last Updated Issue

Jan 28, 2024 7:46 PM

Description

Asphalt pavement and curb in gutter conditions experiencing cracking & settling, appear to be in fair / poor condition.


Driveway width does not appear to adhere to recommended layout or adhere to aerial apparatus fire code requirements.

Existing retaining wall and handrails are damaged. Note: Majority of access drive and wall are over property line, encroachment is identified on existing easement agreements with adjacent property owner.

Apparent drain line resulting in washout of landscape area. Existing utility line partially exposed.

Photos

Sheet







20231120_094144_photo **Cody Lanman** Nov 20, 2023 9:41 AM




20231120_094134_photo **Cody Lanman** Nov 20, 2023 9:41 AM





20231120_094127_photo **Cody Lanman** Nov 20, 2023 9:41 AM



20231120_094116_photo **Cody Lanman** Nov 20, 2023 9:41 AM





20231120_094106_photo **Cody Lanman** Nov 20, 2023 9:41 AM



#33 East Access Drive: Existing pavement, C&G and Retaining wall

Status

Created

Open Dec 5, 2023 9:00 AM clanman@eberly.net

Type

Issue

Last Updated

Jan 28, 2024 7:29 PM

Description


Asphalt pavement and curb in gutter conditions experiencing cracking & settling, appear to be in fair / poor condition.

Driveway width does not appear to adhere to recommended layout or adhere to aerial apparatus fire code requirements.

Existing retaining wall and handrails are damaged. Note: Majority of access drive and wall are over property line, encroachment is identified on existing easement agreements with adjacent property owner.

Photos

Sheet







20231120_094016_photo Cody Lanman Nov 20, 2023 9:40 AM



20231120_094000_photo **Cody Lanman** Nov 20, 2023 9:40 AM





20231120_093954_photo **Cody Lanman** Nov 20, 2023 9:39 AM



#32 East Access Drive: Existing pavement, C&G and Retaining wall

Status Open Created

Dec 5, 2023 9:00 AM

clanman@eberly.net

Type Issue

Last Updated

Jan 28, 2024 7:29 PM

Description


Asphalt pavement and curb in gutter conditions experiencing cracking & settling, appear to be in fair / poor condition.

Driveway width does not appear to adhere to recommended layout or adhere to aerial apparatus fire code requirements.

Existing retaining wall and handrails are damaged. Note: Majority of access drive and wall are over property line, encroachment is identified on existing easement agreements with adjacent property owner.

Photos

Sheet







20231120_093913_photo **Cody Lanman** Nov 20, 2023 9:39 AM



20231120_093906_photo **Cody Lanman** Nov 20, 2023 9:39 AM





20231120_093832_photo **Cody Lanman** Nov 20, 2023 9:38 AM



20231120_093821_photo **Cody Lanman** Nov 20, 2023 9:38 AM





20231120_093811_photo **Cody Lanman** Nov 20, 2023 9:38 AM



#31 East Access Drive: Drop Inlet

Status

Open

Type Issue

Description

Pavement surrounding drop inlet damaged and is not flush with grate cover. Inlet and structure appear to be full of trash and debris.

Created


Dec 5, 2023 9:00 AM clanman@eberly.net

Last Updated

Jan 28, 2024 7:29 PM

Sheet

2





20231120_093748_photo **Cody Lanman** Nov 20, 2023 9:37 AM



20231120_093740_photo **Cody Lanman** Nov 20, 2023 9:37 AM

DCSD - Druid Hills HS Modernization

1798 Haygood Drive Northeast, Atlanta, Georgia





20231120_093727_photo **Cody Lanman** Nov 20, 2023 9:37 AM



#30 Southern Parking Lot: Large Boundary Tree

Status Created

Open Dec 5, 2023 9:00 AM

clanman@eberly.net

Type

Issue Last Updated


Jan 28, 2024 7:15 PM

Description

Existing large boundary tree.

Sheet

2





20231120_093706_photo **Cody Lanman** Nov 20, 2023 9:37 AM



#29 Southern Parking Lot: Existing pavement and C&G

Status Created

Open Dec 5, 2023 9:00 AM

clanman@eberly.net

Type

Issue Last Updated

Jan 28, 2024 7:14 PM

Description

Asphalt pavement and curb in gutter conditions experiencing cracking & settling, appear to be in fair / poor condition.

Lot layout and dimensions do not appear to adhere to recommended layout or code requirements.

Striping is faded or missing in areas.

Existing connection to adjacent property.

Existing light pole base appears damaged.

Photos

Sheet







20231120_093848_photo Cody Lanman Nov 20, 2023 9:38 AM



20231120_093642_photo **Cody Lanman** Nov 20, 2023 9:36 AM





20231120_093635_photo **Cody Lanman** Nov 20, 2023 9:36 AM



20231120_093609_photo **Cody Lanman** Nov 20, 2023 9:36 AM





20231120_093602_photo **Cody Lanman** Nov 20, 2023 9:36 AM



#28 Southern Parking Lot: Large Ash Tree

Status

Open

Type Issue

Description

Large Ash Tree within landscape area. (Tree species indicated are as reflected on 2007 Survey)

Created


Dec 5, 2023 9:00 AM clanman@eberly.net

Last Updated

Jan 28, 2024 7:13 PM

Sheet

2



Photos



20231120_093428_photo **Cody Lanman** Nov 20, 2023 9:34 AM



#27 Southern Parking Lot: Gymnasium Stairs & Sidewalk

Status Open Created
Dec 5, 2023 9:00 AM clanman@eberly.net

Type

Issue Last Updated
Jan 28, 2024 7:10 PM

Description

Existing sidewalk and stairs experiencing cracking and appear to be in fair / poor condition.


Sidewalk and pavement transition uneven in areas posing possible tripping hazard. Significant staining occurring at drop off area.

Photos

Sheet







20231120_093527_photo **Cody Lanman** Nov 20, 2023 9:35 AM



20231120_093520_photo **Cody Lanman** Nov 20, 2023 9:35 AM





20231120_093503_photo **Cody Lanman** Nov 20, 2023 9:35 AM



20231120_093449_photo **Cody Lanman** Nov 20, 2023 9:34 AM






20231120_093439_photo **Cody Lanman** Nov 20, 2023 9:34 AM



20231120_093411_photo **Cody Lanman** Nov 20, 2023 9:34 AM





20231120_093403_photo **Cody Lanman** Nov 20, 2023 9:34 AM



#26 Southern Parking Lot: Pedestrian & Stair Connection

Status Created

Open Dec 5, 2023 8:59 AM clanman@eberly.net

Type

Issue Last Updated

Jan 28, 2024 7:09 PM

Description

Existing sidewalk and stairs experiencing cracking and appear to be in fair condition. Stair handrails do not appear to adhere to standard configuration.

Apparent pedestrian "cut through" path through landscape area.

Photos

Sheet







20231120_093343_photo Cody Lanman Nov 20, 2023 9:33 AM



20231120_093321_photo **Cody Lanman** Nov 20, 2023 9:33 AM





20231120_093314_photo **Cody Lanman** Nov 20, 2023 9:33 AM



20231120_093300_photo **Cody Lanman** Nov 20, 2023 9:33 AM



#25 Southern Parking Lot: Large Oak & Ash Tree

Status

Open

Type Issue

Description

Large Trees within landscape area. (Tree species indicated are as reflected on 2007 Survey) Created


Dec 5, 2023 8:59 AM clanman@eberly.net

Last Updated

Jan 28, 2024 7:12 PM

Sheet

2



Photos



20231120_093241_photo **Cody Lanman** Nov 20, 2023 9:32 AM



#24 Southern Parking Lot: Existing pavement and C&G

Status

Created

Open

Nov 30, 2023 6:44 PM clanman@eberly.net

Type

Issue

Last Updated

Jan 28, 2024 7:13 PM

Description


Asphalt pavement and curb in gutter conditions experiencing cracking & settling, appear to be in fair / poor condition.

Lot layout and dimensions do not appear to adhere to recommended layout or code requirements.

Striping is faded or missing in areas.

Photos

Sheet







20231120_093217_photo Cody Lanman Nov 20, 2023 9:32 AM



20231120_093210_photo **Cody Lanman** Nov 20, 2023 9:32 AM

1798 Haygood Drive Northeast, Atlanta, Georgia





20231120_093204_photo **Cody Lanman**

Nov 20, 2023 9:32 AM



#23 Southern Parking Lot: Existing pavement and Existing Retaining Wall

Status

Created

Open

Nov 30, 2023 6:44 PM clanman@eberly.net

Type

Issue

Last Updated

Jan 28, 2024 7:03 PM

Description

Asphalt pavement and curb in gutter conditions experiencing cracking & settling, appear to be in fair / poor condition.

Lot layout and dimensions do not appear to adhere to recommended layout or code requirements.

Striping is faded or missing in areas.

Documenting existing retaining wall.

Photos

Sheet







20231120_093135_photo **Cody Lanman** Nov 20, 2023 9:31 AM



20231120_093129_photo **Cody Lanman** Nov 20, 2023 9:31 AM





20231120_093119_photo **Cody Lanman** Nov 20, 2023 9:31 AM



#22 Southern Parking Lot: Existing pavement and Sewer manhole

Status

Created

Open

Nov 30, 2023 6:44 PM

clanman@eberly.net

Type

Last Updated

Jan 28, 2024 7:03 PM

Issue

Description

Asphalt pavement and curb in gutter conditions experiencing cracking & settling, appear to be in fair / poor condition.

Lot layout and dimensions do not appear to adhere to recommended layout or code requirements.

Striping is faded or missing in areas.

Existing Sewer Manhole. Pavement surrounding drop inlet damaged and is not flush with cover.

Photos

Sheet







20231120_093053_photo Cody Lanman Nov 20, 2023 9:30 AM



20231120_093044_photo **Cody Lanman** Nov 20, 2023 9:30 AM





20231120_093025_photo **Cody Lanman** Nov 20, 2023 9:30 AM



#21 Southern Parking Lot: Existing Light Poles

Status Created

Open Nov 30, 2023 6:44 PM

clanman@eberly.net

Type Issue Last Updated

Jan 28, 2024 7:01 PM


Description

Documentation of existing

light poles

Sheet

2



Photos



20231120_093005_photo **Cody Lanman** Nov 20, 2023 9:30 AM



#20 Southern Parking Lot: Existing pavement and C&G

Status Created

Open Nov 30, 2023 6:44 PM

clanman@eberly.net

Type

Issue Last Updated

Jan 28, 2024 7:01 PM

Description

Asphalt pavement and curb in gutter conditions experiencing cracking & settling, appear to be in fair / poor condition.

Lot layout and dimensions do not appear to adhere to recommended layout or code requirements.

Striping is faded or missing in areas.

Photos


Sheet







20231120_092941_photo **Cody Lanman** Nov 20, 2023 9:29 AM



20231120_092934_photo **Cody Lanman** Nov 20, 2023 9:29 AM





20231120_092927_photo **Cody Lanman** Nov 20, 2023 9:29 AM



#19 Southern Parking Lot: Existing pavement and Existing Retaining Wall

Created

Status

Open Nov 30, 2023 6:44 PM

clanman@eberly.net

Type

Issue Last Updated

Jan 28, 2024 7:00 PM

Description

Asphalt pavement and curb in gutter conditions experiencing cracking & settling, appear to be in fair / poor condition.

Lot layout and dimensions do not appear to adhere to recommended layout or code requirements.

Striping is faded or missing in areas.

Documenting existing retaining wall.

Photos

Sheet







20231120_092912_photo **Cody Lanman** Nov 20, 2023 9:29 AM



20231120_092904_photo **Cody Lanman** Nov 20, 2023 9:29 AM



#18 Southern Parking Lot: Dumpsters

Status Created

Open Nov 30, 2023 6:44 PM

clanman@eberly.net

Type Issue Last Updated


Jan 28, 2024 6:59 PM

Description

Dumpster and recycling bin. Pavement around dumpsters appears damaged. No protection / approach pad provided at dumpster locations.

Sheet

2



Photos



20231120_092847_photo **Cody Lanman** Nov 20, 2023 9:28 AM



20231120_092839_photo **Cody Lanman** Nov 20, 2023 9:28 AM





20231120_092830_photo **Cody Lanman** Nov 20, 2023 9:28 AM



#17 Southern Parking Lot: Existing pavement and C&G

Status Created

Open Nov 30, 2023 6:44 PM

clanman@eberly.net

Type

Issue Last Updated

Jan 28, 2024 7:00 PM

Description


Asphalt pavement and curb in gutter conditions experiencing cracking & settling, appear to be in fair / poor condition.

Lot layout and dimensions do not appear to adhere to recommended layout or code requirements.

Striping is faded or missing in areas.

Photos

Sheet







20231120_092812_photo **Cody Lanman** Nov 20, 2023 9:28 AM



20231120_092801_photo **Cody Lanman** Nov 20, 2023 9:28 AM



#16 Southern Parking Lot: Existing Storm Structure

Status Created

Open Nov 30, 2023 6:44 PM

clanman@eberly.net

Type

Issue Last Updated

Jan 28, 2024 7:02 PM

Description

Existing Storm Junction Box. Pavement surrounding drop inlet damaged and is not flush with cover.

Structure appear to be full of trash and debris.

Photos

Sheet







20231120_092740_photo **Cody Lanman** Nov 20, 2023 9:27 AM



#15 Southern Parking Lot: Existing pavement and C&G

Status Created

Open Nov 30, 2023 6:43 PM

clanman@eberly.net

Type

Issue Last Updated

Jan 28, 2024 6:57 PM

Description

Asphalt pavement and curb in gutter conditions experiencing cracking & settling, appear to be in fair / poor condition.

Lot layout and dimensions do not appear to adhere to recommended layout or code requirements.

Striping is faded or missing in areas.

Photos

Sheet







20231120_092725_photo **Cody Lanman** Nov 20, 2023 9:27 AM



20231120_092719_photo **Cody Lanman** Nov 20, 2023 9:27 AM





20231120_092713_photo **Cody Lanman** Nov 20, 2023 9:27 AM



20231120_092704_photo **Cody Lanman** Nov 20, 2023 9:27 AM



#14 Southern Parking Lot: Boundary Tree

Status Created

Open Nov 30, 2023 6:43 PM

clanman@eberly.net

Type

Issue Last Updated


Jan 28, 2024 6:53 PM

Description

Existing large boundary tree.

Sheet

2





20231120_092643_photo **Cody Lanman** Nov 20, 2023 9:26 AM



#13 Southern Parking Lot: Large Boundary Tree

Status Created

Open Nov 30, 2023 6:43 PM

clanman@eberly.net

Type

Issue Last Updated


Jan 28, 2024 6:53 PM

Description

Existing large boundary tree.

Sheet

2





20231120_092627_photo **Cody Lanman** Nov 20, 2023 9:26 AM



#12 Southern Parking Lot: Existing pavement and C&G

Status Created

Open Nov 30, 2023 6:43 PM

clanman@eberly.net

Type

Issue Last Updated

Jan 28, 2024 6:57 PM

Description

Asphalt pavement and curb in gutter conditions experiencing cracking & settling, appear to be in good / fair / poor condition.

Striping is faded or missing in areas.

Photos

Sheet







20231120_092608_photo **Cody Lanman** Nov 20, 2023 9:26 AM



20231120_092559_photo **Cody Lanman** Nov 20, 2023 9:26 AM

DCSD - Druid Hills HS Modernization

1798 Haygood Drive Northeast, Atlanta, Georgia





20231120_092552_photo **Cody Lanman** Nov 20, 2023 9:25 AM



#11 Southern Parking Lot Entrance Drive: Existing Power Pole

Status

Created

Open Nov 30, 2023 6:43 PM

clanman@eberly.net

Type

Issue Last Updated

Jan 28, 2024 6:50 PM

Description

Existing power pole with utility box at Southern parking lot landscape island.

Sheet

2





20231120_092529_photo **Cody Lanman** Nov 20, 2023 9:25 AM



#10 Southern Parking Lot Entrance Drive: Existing pavement

Status Created

Open Nov 30, 2023 6:43 PM

clanman@eberly.net

Type

Issue Last Updated

Jan 28, 2024 6:48 PM

Description


Asphalt driveway experiencing some cracking & settling, appear to be in good / fair condition.

Granite curbing sinking and flush with adjacent pavement and landscape areas.

Driveway width and slopes does not appear to adhere to standard recommendations and does not appear to meet code dimensions.

Photos

Sheet







20231120_092501_photo Cody Lanman Nov 20, 2023 9:25 AM



20231120_092409_photo Cody Lanman Nov 20, 2023 9:24 AM



#9 Southern Parking Lot Entrance Drive: Existing pavement, Sidewalk, C&G and Utilities

Status

Created

Open

Nov 30, 2023 6:43 PM clanman@eberly.net

Type

Issue

Last Updated

Jan 28, 2024 6:47 PM

Description

Asphalt driveway and curb in gutter conditions experiencing some cracking & settling, appear to be in good / fair condition.

Sidewalks experiencing some cracking and chipping, appear in fair condition.

Driveway configuration and connection to right-of-way not does not appear to adhere to standard recommendations and does not appear to meet code dimensions.

ADA curb ramps and crosswalk do not appear to be compliant, and crosswalk striping faded.

Existing sanitary sewer manhole.

Photos

Sheet







20231120_092354_photo **Cody Lanman** Nov 20, 2023 9:23 AM



20231120_092331_photo **Cody Lanman** Nov 20, 2023 9:23 AM





20231120_092324_photo Cody Lanman Nov 20, 2023 9:23 AM



20231120_092309_photo **Cody Lanman** Nov 20, 2023 9:23 AM



#8 Southern Parking Lot Entrance Drive: Large Oak Tree

Status

Created

Open

Nov 30, 2023 6:43 PM clanman@eberly.net

Type

Issue

Last Updated

Jan 28, 2024 10:31 PM

Description

Large Oak Tree (+/- 40"). (Tree species indicated are as reflected on 2007 Survey)

Sheet

2





20231120_092256_photo **Cody Lanman** Nov 20, 2023 9:22 AM



#7 Haygood Drive & North Decatur Drive Intersection

Status

Open

Type Issue

Description

Existing conditions at intersection of Haygood Drive and North Decatur Road

Created

Nov 30, 2023 6:43 PM clanman@eberly.net

Last Updated

Jan 28, 2024 6:40 PM

Sheet

2





20231120_092229_photo **Cody Lanman** Nov 20, 2023 9:22 AM



#6 Southern Parking Lot Exit Drive: Drop Inlet

Status Created

Open Nov 30, 2023 6:43 PM

clanman@eberly.net

Type

Issue Last Updated

Jan 28, 2024 6:39 PM

Description

Existing drop inlet not reflected on survey. Pavement surrounding drop inlet damaged and is not flush with grate cover.

Inlet not aligned with drainage pattern. Inlet and structure appear to be full of trash and debris.

Photos

Sheet







20231120_092211_photo **Cody Lanman** Nov 20, 2023 9:22 AM



20231120_092158_photo **Cody Lanman** Nov 20, 2023 9:22 AM



#5 Southern Parking Lot Exit Drive: Existing pavement, Sidewalk, and C&G

Status Created

Open Nov 30, 2023 6:43 PM

clanman@eberly.net

Type

ISSUE Last Updated

Jan 28, 2024 6:47 PM

Description

Asphalt driveway and curb in gutter conditions experiencing some cracking & settling, appear to be in good / fair condition.


Sidewalks experiencing some cracking and chipping, appear in good to fair condition.

Driveway configuration and connection to right-of-way not does not appear to adhere to standard recommendations and does not appear to meet code dimensions.

ADA curb ramps do not appear to be compliant and crosswalks striping faded.

Photos

Sheet







20231120_092134_photo **Cody Lanman** Nov 20, 2023 9:21 AM



20231120_092127_photo **Cody Lanman** Nov 20, 2023 9:21 AM





20231120_092115_photo **Cody Lanman** Nov 20, 2023 9:21 AM



20231120_092109_photo **Cody Lanman** Nov 20, 2023 9:21 AM



#4 Southern Right-of-Way Parking: Existing Utilities

Status Created

Open Nov 30, 2023 6:43 PM

clanman@eberly.net

Type

Issue Last Updated

Jan 28, 2024 6:26 PM

Description

Location of existing power pole and guy wires servicing


site.

Existing benchmark.

Signage damaged / falling.

Photos

Sheet







20231120_092051_photo Cody Lanman Nov 20, 2023 9:20 AM



20231120_092042_photo **Cody Lanman** Nov 20, 2023 9:20 AM





20231120_092030_photo **Cody Lanman** Nov 20, 2023 9:20 AM



20231120_092024_photo **Cody Lanman** Nov 20, 2023 9:20 AM



#3 Southern Right-of-Way Parking: Existing pavement, Sidewalk and C&G

Status

Created

Open

Nov 30, 2023 6:43 PM clanman@eberly.net

Type

Issue

Last Updated

Jan 28, 2024 6:25 PM

Description

Southern right-of-way street parking.


Asphalt pavement and curb in gutter conditions experiencing some cracking & settling, appear to be in generally good condition. Parking striping very faded.

Sidewalks experiencing significant cracking and chipping, appear in fair condition.

Existing signage damaged & very close the sidewalk and curb.

Photos

Sheet







20231120_092008_photo **Cody Lanman** Nov 20, 2023 9:20 AM



20231120_091944_photo **Cody Lanman** Nov 20, 2023 9:19 AM





20231120_091932_photo **Cody Lanman** Nov 20, 2023 9:19 AM



20231120_091924_photo **Cody Lanman** Nov 20, 2023 9:19 AM



#2 Entrance Drop-off Driveway: Existing Utilities

Status

Open

Type Issue

Description

Location of existing sanitary sewer connection and rightof-way stormwater drainage that continues onto Highschool site. Created

Nov 30, 2023 6:43 PM clanman@eberly.net

Last Updated

Jan 28, 2024 6:13 PM

Sheet

2





20231120_091752_photo **Cody Lanman** Nov 20, 2023 9:17 AM



20231120_091734_photo Cody Lanman Nov 20, 2023 9:17 AM



#1 Entrance Drop-off Driveway: Existing Pavement, Sidewalk and C&G

Status Open Created Nov 30, 2023 6:42 PM

clanman@eberly.net

Type

Issue Last Updated

Jan 28, 2024 6:11 PM

Description

Observations & conditions of existing entrance drop off driveway.

Asphalt driveway and curb in gutter conditions experiencing some cracking & settling, appear to be in generally good condition.

Sidewalks experiencing some cracking and chipping, appear in good to fair condition.

Driveway does not have ADA curb ramps or crosswalks for pedestrian safety / accessibility.

Existing signage damaged & very close the sidewalk and curb.

Photos

Sheet







20231120_091858_photo Cody Lanman Nov 20, 2023 9:18 AM



20231120_091849_photo **Cody Lanman** Nov 20, 2023 9:18 AM





20231120_091841_photo **Cody Lanman** Nov 20, 2023 9:18 AM



20231120_091826_photo **Cody Lanman** Nov 20, 2023 9:18 AM





20231120_091818_photo **Cody Lanman** Nov 20, 2023 9:18 AM



20231120_091810_photo **Cody Lanman** Nov 20, 2023 9:18 AM





20231120_091658_photo **Cody Lanman** Nov 20, 2023 9:17 AM



20231120_091647_photo **Cody Lanman** Nov 20, 2023 9:16 AM