



June 7, 2017

**Via E-Mail: Joshua\_I\_williams@dekalbschoolsga.org**

Mr. Joshua L. Williams, MBA, MSM, PMP  
Chief Operations Officer  
DeKalb County School District  
Operations Division  
Sam Moss Service Center  
1780 Montreal Road  
Tucker, Georgia 30084

**Re: Lead in Drinking Water Sample Results  
Peachcrest Elementary School (Facility ID #5416)  
1530 Joy Lane, Decatur, Georgia 30032  
AEM Project No. 1561-1601**

Dear Mr. Williams:

Atlanta Environmental Management, Inc. (AEM) is pleased to provide the DeKalb County School District (DCSD) an electronic copy of the Lead in Drinking Water Sample Results for Peachcrest Elementary School (Facility ID #5416). Samples were collected on May 12 and May 19, 2017. Laboratory analytical results were received from Analytical Environmental Services, Inc., on May 26 and June 5, 2017.

## FINDINGS

AEM collected 198 drinking water samples from 86 sources at Peachcrest Elementary School (Facility ID #5416), including two duplicate samples. A description of the drinking water outlets sampled and a summary of sample analytical results are provided in the attached table.

None of the samples collected and analyzed contained lead at a concentration equal to or above EPA's action level of 15 parts per billion.

We appreciate your selection of AEM for this project. If you have any questions, please do not hesitate to contact us.

Sincerely,

**Atlanta Environmental Management, Inc.**

  
Leona Miles, CHMM  
Senior Project Manager

  
Janet T. Hart  
President

/krf

cc: Daniel Drake (DCSD)  
Tracee Hill (DCSD)  
Sandra Glen (DeKalb County Watershed Management)  
Ryan Cira (DeKalb Board of Health)

Attachment: Table

**Table 1. Summary of Lead in Drinking Water Laboratory Analytical Results**  
**Peachcrest Elementary School**  
 1530 Joy Lane, Decatur, GA 30032



Sample ID*	Sample Location Description	Sample Date & Time	Lead Test Results (ppb)
5416-051217-DF-001-A	Initial Draw sample; Right wall mounted Elkay Drinking Fountain right inside Gym entrance	5/12/17 5:18 AM	None Detected
5416-051217-DF-001-B	Flush sample; Right wall mounted Elkay Drinking Fountain right inside Gym entrance	5/12/17 5:19 AM	None Detected
5416-051217-DF-002-A	Initial Draw sample; Middle wall mounted Elkay Drinking Fountain right inside Gym entrance	5/12/17 5:20 AM	None Detected
5416-051217-DF-002-B	Flush sample; Middle wall mounted Elkay Drinking Fountain right inside Gym entrance	5/12/17 5:21 AM	None Detected
5416-051217-DF-003-A	Initial Draw sample; Left wall mounted Elkay Drinking Fountain right inside Gym entrance	5/12/17 5:22 AM	None Detected
5416-051217-DF-003-B	Flush sample; Left wall mounted Elkay Drinking Fountain right inside Gym entrance	5/12/17 5:23 AM	None Detected
5416-051217-DF-004-A	Initial Draw sample; Right wall mounted Elkay Drinking Fountain in hallway immediately across from Gym entrance	5/12/17 5:09 AM	None Detected
5416-051217-DF-004-B	Flush sample; Right wall mounted Elkay Drinking Fountain in hallway immediately across from Gym entrance	5/12/17 5:10 AM	None Detected
5416-051217-DF-005-A	Initial Draw sample; Middle wall mounted Elkay Drinking Fountain in hallway immediately across from Gym entrance	5/12/17 5:11 AM	None Detected
5416-051217-DF-005-B	Flush sample; Middle wall mounted Elkay Drinking Fountain in hallway immediately across from Gym entrance	5/12/17 5:12 AM	None Detected
5416-051217-DF-006-A	Initial Draw sample; Left wall mounted Elkay Drinking Fountain in hallway immediately across from Gym entrance	5/12/17 5:13 AM	None Detected
5416-051217-DF-006-B	Flush sample; Left wall mounted Elkay Drinking Fountain in hallway immediately across from Gym entrance	5/12/17 5:14 AM	None Detected
5416-051217-DF-007-A	Initial Draw sample; Left wall mounted Elkay Drinking Fountain in hallway across from Counselor's Rm 2702	5/12/17 5:00 AM	None Detected
5416-051217-DF-007-B	Flush sample; Left wall mounted Elkay Drinking Fountain in hallway across from Counselor's Rm 2702	5/12/17 5:01 AM	None Detected
5416-051217-DF-008-A	Initial Draw sample; Middle wall mounted Elkay Drinking Fountain in hallway across from Counselor's Rm 2702	5/12/17 5:02 AM	12.3

**Table 1. Summary of Lead in Drinking Water Laboratory Analytical Results**  
**Peachcrest Elementary School**  
 1530 Joy Lane, Decatur, GA 30032



Sample ID*	Sample Location Description	Sample Date & Time	Lead Test Results (ppb)
5416-051217-DF-008-B	Flush sample; Middle wall mounted Elkay Drinking Fountain in hallway across from Counselor's Rm 2702	5/12/17 5:03 AM	None Detected
5416-051217-DF-009-A	Initial Draw sample; Right wall mounted Elkay Drinking Fountain in hallway across from Counselor's Rm 2702	5/12/17 5:04 AM	None Detected
5416-051217-DF-009-B	Flush sample; Right wall mounted Elkay Drinking Fountain in hallway across from Counselor's Rm 2702	5/12/17 5:05 AM	None Detected
5416-051217-DF-010-A	Initial Draw sample; Upper Left wall mounted Elkay Drinking Fountain in hallway near Rm 2010	5/12/17 5:49 AM	None Detected
5416-051217-DF-010-B	Flush sample; Upper Left wall mounted Elkay Drinking Fountain in hallway near Rm 2010	5/12/17 5:50 AM	None Detected
5416-051217-DF-011-A	Initial Draw sample; Middle wall mounted Elkay Drinking Fountain in hallway near Rm 2010	5/12/17 5:52 AM	None Detected
5416-051217-DF-011-B	Flush sample; Middle wall mounted Elkay Drinking Fountain in hallway near Rm 2010	5/12/17 5:53 AM	None Detected
5416-051217-DF-012-A	Initial Draw sample; Lower Right wall mounted Elkay Drinking Fountain in hallway near Rm 2010	5/12/17 5:54 AM	None Detected
5416-051217-DF-012-B	Flush sample; Lower Right wall mounted Elkay Drinking Fountain in hallway near Rm 2010	5/12/17 5:55 AM	None Detected
5416-051217-DF-013-A	Initial Draw sample; Lower Right wall mounted Elkay Drinking Fountain in hallway near Rm 2206	5/12/17 5:23 AM	None Detected
5416-051217-DF-013-B	Flush sample; Lower Right wall mounted Elkay Drinking Fountain in hallway near Rm 2206	5/12/17 5:24 AM	None Detected
5416-051217-DF-014-A	Initial Draw sample; Middle wall mounted Elkay Drinking Fountain in hallway near Rm 2206	5/12/17 5:21 AM	None Detected
5416-051217-DF-014-B	Flush sample; Middle wall mounted Elkay Drinking Fountain in hallway near Rm 2206	5/12/17 5:22 AM	None Detected
5416-051217-DF-015-A	Initial Draw sample; Upper Left wall mounted Elkay Drinking Fountain in hallway near Rm 2206	5/12/17 5:19 AM	None Detected
5416-051217-DF-015-B	Flush sample; Upper Left wall mounted Elkay Drinking Fountain in hallway near Rm 2206	5/12/17 5:20 AM	None Detected

**Table 1. Summary of Lead in Drinking Water Laboratory Analytical Results**  
**Peachcrest Elementary School**  
 1530 Joy Lane, Decatur, GA 30032



Sample ID*	Sample Location Description	Sample Date & Time	Lead Test Results (ppb)
5416-051217-DF-016-A	Initial Draw sample; Left wall mounted Elkay Drinking Fountain in hallway near Rm 3001	5/12/17 5:27 AM	None Detected
5416-051217-DF-016-B	Flush sample; Left wall mounted Elkay Drinking Fountain in hallway near Rm 3001	5/12/17 5:28 AM	None Detected
5416-051217-DF-017-A	Initial Draw sample; Middle wall mounted Elkay Drinking Fountain in hallway near Rm 3001	5/12/17 5:29 AM	None Detected
5416-051217-DF-017-B	Flush sample; Middle wall mounted Elkay Drinking Fountain in hallway near Rm 3001	5/12/17 5:30 AM	None Detected
5416-051217-DF-018-A	Initial Draw sample; Right wall mounted Elkay Drinking Fountain in hallway near Rm 3001	5/12/17 5:31 AM	None Detected
5416-051217-DF-018-B	Flush sample; Right wall mounted Elkay Drinking Fountain in hallway near Rm 3001	5/12/17 5:32 AM	None Detected
5416-051217-DF-019-A	Initial Draw sample; Left wall mounted Elkay Drinking Fountain in hallway near Rm 1003	5/12/17 5:01 AM	None Detected
5416-051217-DF-019-B	Flush sample; Left wall mounted Elkay Drinking Fountain in hallway near Rm 1003	5/12/17 5:02 AM	None Detected
5416-051217-DF-020-A	Initial Draw sample; Middle wall mounted Elkay Drinking Fountain in hallway near Rm 1003	5/12/17 5:03 AM	None Detected
5416-051217-DF-020-B	Flush sample; Middle wall mounted Elkay Drinking Fountain in hallway near Rm 1003	5/12/17 5:04 AM	None Detected
5416-051217-DF-021-A	Initial Draw sample; Right wall mounted Elkay Drinking Fountain in hallway near Rm 1003	5/12/17 5:05 AM	None Detected
5416-051217-DF-021-B	Flush sample; Right wall mounted Elkay Drinking Fountain in hallway near Rm 1003	5/12/17 5:06 AM	None Detected
5416-051217-DF-022-A	Initial Draw sample; Left wall mounted Elkay Drinking Fountain in hallway near Rm 1206	5/12/17 5:23 AM	None Detected
5416-051217-DF-022-B	Flush sample; Left wall mounted Elkay Drinking Fountain in hallway near Rm 1206	5/12/17 5:24 AM	None Detected
5416-051217-DF-023-A	Initial Draw sample; Middle wall mounted Elkay Drinking Fountain in hallway near Rm 1206	5/12/17 5:25 AM	None Detected

**Table 1. Summary of Lead in Drinking Water Laboratory Analytical Results**  
**Peachcrest Elementary School**  
1530 Joy Lane, Decatur, GA 30032



Sample ID*	Sample Location Description	Sample Date & Time	Lead Test Results (ppb)
5416-051217-DF-023-B	Flush sample; Middle wall mounted Elkay Drinking Fountain in hallway near Rm 1206	5/12/17 5:26 AM	None Detected
5416-051217-DF-024-A	Initial Draw sample; Right wall mounted Elkay Drinking Fountain in hallway near Rm 1206	5/12/17 5:27 AM	None Detected
5416-051217-DF-024-B	Flush sample; Right wall mounted Elkay Drinking Fountain in hallway near Rm 1206	5/12/17 5:28 AM	None Detected
5416-051217-KS-001-A	Initial Draw sample; Sink with bubbler in Rm 2214; Sampled faucet	5/12/17 5:01 AM	None Detected
5416-051217-KS-001-B	Flush sample; Sink with bubbler in Rm 2214; Sampled faucet	5/12/17 5:02 AM	None Detected
5416-051217-KS-001-A2	Initial Draw sample; Sink with bubbler in Rm 2214; Sampled bubbler	5/12/17 5:03 AM	None Detected
5416-051217-KS-001-B2	Flush sample; Sink with bubbler in Rm 2214; Sampled bubbler	5/12/17 5:04 AM	None Detected
5416-051217-KS-002-A	Initial Draw sample; Sink with bubbler in Rm 2212; Sampled faucet	5/12/17 5:22 AM	None Detected
5416-051217-KS-002-B	Flush sample; Sink with bubbler in Rm 2212; Sampled faucet	5/12/17 5:23 AM	None Detected
5416-051217-KS-002-A2	Initial Draw sample; Sink with bubbler in Rm 2212; Sampled bubbler	5/12/17 5:24 AM	None Detected
5416-051217-KS-002-B2	Flush sample; Sink with bubbler in Rm 2212; Sampled bubbler	5/12/17 5:25 AM	None Detected
5416-051217-KS-003-A	Initial Draw sample; Sink with bubbler in Rm 2210; Sampled faucet	5/12/17 5:37 AM	None Detected
5416-051217-KS-003-B	Flush sample; Sink with bubbler in Rm 2210; Sampled faucet	5/12/17 5:38 AM	None Detected
5416-051217-KS-003-A2	Initial Draw sample; Sink with bubbler in Rm 2210; Sampled bubbler	5/12/17 5:39 AM	None Detected
5416-051217-KS-003-B2	Flush sample; Sink with bubbler in Rm 2210; Sampled bubbler	5/12/17 5:40 AM	None Detected
5416-051217-KS-004-A	Initial Draw sample; Sink with bubbler in Rm 2208; Sampled faucet	5/12/17 5:41 AM	None Detected
5416-051217-KS-004-B	Flush sample; Sink with bubbler in Rm 2208; Sampled faucet	5/12/17 5:42 AM	None Detected
5416-051217-KS-004-A2	Initial Draw sample; Sink with bubbler in Rm 2208; Sampled bubbler	5/12/17 5:43 AM	None Detected
5416-051217-KS-004-B2	Flush sample; Sink with bubbler in Rm 2208; Sampled bubbler	5/12/17 5:44 AM	None Detected
5416-051217-KS-005-A	Initial Draw sample; Sink with bubbler in Rm 2206; Sampled faucet	5/12/17 5:55 AM	None Detected
5416-051217-KS-005-B	Flush sample; Sink with bubbler in Rm 2206; Sampled faucet	5/12/17 5:56 AM	None Detected
5416-051217-KS-005-A2	Initial Draw sample; Sink with bubbler in Rm 2206; Sampled bubbler	5/12/17 5:57 AM	None Detected
5416-051217-KS-005-B2	Flush sample; Sink with bubbler in Rm 2206; Sampled bubbler	5/12/17 5:58 AM	None Detected
5416-051217-KS-006-A	Initial Draw sample; Sink with bubbler in Rm 2204; Sampled faucet	5/12/17 5:28 AM	None Detected
5416-051217-KS-006-B	Flush sample; Sink with bubbler in Rm 2204; Sampled faucet	5/12/17 5:29 AM	None Detected
5416-051217-KS-007-A	Initial Draw sample; Sink with bubbler in Rm 2202; Sampled faucet	5/12/17 5:32 AM	None Detected
5416-051217-KS-007-B	Flush sample; Sink with bubbler in Rm 2202; Sampled faucet	5/12/17 5:33 AM	None Detected
5416-051217-KS-008-A	Initial Draw sample; Sink with bubbler in Rm 2209; Sampled faucet	5/12/17 5:49 AM	None Detected

**Table 1. Summary of Lead in Drinking Water Laboratory Analytical Results**  
**Peachcrest Elementary School**  
 1530 Joy Lane, Decatur, GA 30032



Sample ID*	Sample Location Description	Sample Date & Time	Lead Test Results (ppb)
5416-051217-KS-008-B	Flush sample; Sink with bubbler in Rm 2209; Sampled faucet	5/12/17 5:50 AM	None Detected
5416-051217-KS-008-A2	Initial Draw sample; Sink with bubbler in Rm 2209; Sampled bubbler	5/12/17 5:51 AM	None Detected
5416-051217-KS-008-B2	Flush sample; Sink with bubbler in Rm 2209; Sampled bubbler	5/12/17 5:52 AM	None Detected
5416-051217-KS-009-A	Initial Draw sample; Sink with bubbler in Rm 2211; Sampled faucet	5/12/17 5:45 AM	None Detected
5416-051217-KS-009-B	Flush sample; Sink with bubbler in Rm 2211; Sampled faucet	5/12/17 5:46 AM	None Detected
5416-051217-KS-009-A2	Initial Draw sample; Sink with bubbler in Rm 2211; Sampled bubbler	5/12/17 5:47 AM	None Detected
5416-051217-KS-009-B2	Flush sample; Sink with bubbler in Rm 2211; Sampled bubbler	5/12/17 5:48 AM	None Detected
5416-051217-KS-010-A	Initial Draw sample; Sink with bubbler in Rm 2213; Sampled faucet	5/12/17 5:32 AM	None Detected
5416-051217-KS-010-B	Flush sample; Sink with bubbler in Rm 2213; Sampled faucet	5/12/17 5:33 AM	None Detected
5416-051217-KS-010-A2	Initial Draw sample; Sink with bubbler in Rm 2213; Sampled bubbler	5/12/17 5:34 AM	None Detected
5416-051217-KS-010-B2	Flush sample; Sink with bubbler in Rm 2213; Sampled bubbler	5/12/17 5:35 AM	None Detected
5416-051217-KS-011-A	Initial Draw sample; Sink with bubbler in Rm 2215; Sampled faucet	5/12/17 5:27 AM	None Detected
5416-051217-KS-011-B	Flush sample; Sink with bubbler in Rm 2215; Sampled faucet	5/12/17 5:28 AM	None Detected
5416-051217-KS-011-A2	Initial Draw sample; Sink with bubbler in Rm 2215; Sampled bubbler	5/12/17 5:29 AM	None Detected
5416-051217-KS-011-B2	Flush sample; Sink with bubbler in Rm 2215; Sampled bubbler	5/12/17 5:30 AM	None Detected
5416-051217-KS-012-A	Initial Draw sample; Sink with bubbler in Rm 2111; Sampled faucet	5/12/17 5:14 AM	None Detected
5416-051217-KS-012-B	Flush sample; Sink with bubbler in Rm 2111; Sampled faucet	5/12/17 5:15 AM	None Detected
5416-051217-KS-013-A	Initial Draw sample; Sink with bubbler in Rm 2109; Sampled faucet	5/12/17 5:10 AM	None Detected
5416-051217-KS-013-B	Flush sample; Sink with bubbler in Rm 2109; Sampled faucet	5/12/17 5:11 AM	None Detected
5416-051217-KS-014-A	Initial Draw sample; Sink with bubbler in Rm 2107; Sampled faucet	5/12/17 5:06 AM	None Detected
5416-051217-KS-014-B	Flush sample; Sink with bubbler in Rm 2107; Sampled faucet	5/12/17 5:07 AM	None Detected
5416-051217-KS-015-A	Initial Draw sample; Sink with bubbler in Rm 2105; Sampled faucet	5/12/17 5:03 AM	None Detected
5416-051217-KS-015-B	Flush sample; Sink with bubbler in Rm 2105; Sampled faucet	5/12/17 5:04 AM	None Detected
5416-051217-KS-016-A	Initial Draw sample; Sink with bubbler in Rm 2104; Sampled faucet	5/12/17 5:45 AM	None Detected
5416-051217-KS-016-B	Flush sample; Sink with bubbler in Rm 2104; Sampled faucet	5/12/17 5:46 AM	None Detected
5416-051217-KS-017-A	Initial Draw sample; Sink with bubbler in Rm 2108; Sampled faucet	5/12/17 5:41 AM	None Detected
5416-051217-KS-017-B	Flush sample; Sink with bubbler in Rm 2108; Sampled faucet	5/12/17 5:42 AM	None Detected
5416-051217-KS-018-A	Initial Draw sample; Sink with bubbler in Rm 2110; Sampled faucet	5/12/17 5:38 AM	None Detected
5416-051217-KS-018-B	Flush sample; Sink with bubbler in Rm 2110; Sampled faucet	5/12/17 5:39 AM	None Detected
5416-051217-KS-019-A	Initial Draw sample; Sink with bubbler in Rm 2112; Sampled faucet	5/12/17 5:35 AM	None Detected
5416-051217-KS-019-B	Flush sample; Sink with bubbler in Rm 2112; Sampled faucet	5/12/17 5:36 AM	None Detected



**Table 1. Summary of Lead in Drinking Water Laboratory Analytical Results**  
**Peachcrest Elementary School**  
 1530 Joy Lane, Decatur, GA 30032



Sample ID*	Sample Location Description	Sample Date & Time	Lead Test Results (ppb)
5416-051217-KS-020-A	Initial Draw sample; Sink with bubbler in Rm 2004; Sampled faucet	5/12/17 5:35 AM	None Detected
5416-051217-KS-020-B	Flush sample; Sink with bubbler in Rm 2004; Sampled faucet	5/12/17 5:36 AM	None Detected
5416-051217-KS-021-A	Initial Draw sample; Sink with bubbler in Rm 2008; Sampled faucet	5/12/17 5:40 AM	None Detected
5416-051217-KS-021-B	Flush sample; Sink with bubbler in Rm 2008; Sampled faucet	5/12/17 5:41 AM	None Detected
5416-051217-KS-021-A2	Initial Draw sample; Sink with bubbler in Rm 2008; Sampled bubbler	5/12/17 5:42 AM	None Detected
5416-051217-KS-021-B2	Flush sample; Sink with bubbler in Rm 2008; Sampled bubbler	5/12/17 5:43 AM	None Detected
5416-051217-KS-022-A	Initial Draw sample; Sink with bubbler in Rm 2010; Sampled faucet	5/12/17 5:46 AM	None Detected
5416-051217-KS-022-B	Flush sample; Sink with bubbler in Rm 2010; Sampled faucet	5/12/17 5:47 AM	None Detected
5416-051217-KS-022-A2	Initial Draw sample; Sink with bubbler in Rm 2010; Sampled bubbler	5/12/17 5:48 AM	None Detected
5416-051217-KS-022-B2	Flush sample; Sink with bubbler in Rm 2010; Sampled bubbler	5/12/17 5:49 AM	None Detected
5416-051917-KS-023-A	Initial Draw sample; Sink with bubbler in Rm 3205; Sampled faucet	5/19/17 5:21 AM	None Detected
5416-051917-KS-023-B	Flush sample; Sink with bubbler in Rm 3205; Sampled faucet	5/19/17 5:22 AM	None Detected
5416-051917-KS-024-A	Initial Draw sample; Sink with bubbler in Rm 3113; Sampled faucet	5/19/17 5:18 AM	None Detected
5416-051917-KS-024-B	Flush sample; Sink with bubbler in Rm 3113; Sampled faucet	5/19/17 5:19 AM	None Detected
5416-051917-KS-025-A	Initial Draw sample; Sink with bubbler in Rm 3111; Sampled faucet	5/19/17 5:14 AM	None Detected
5416-051917-KS-025-B	Flush sample; Sink with bubbler in Rm 3111; Sampled faucet	5/19/17 5:15 AM	None Detected
5416-051917-KS-026-A	Initial Draw sample; Sink with bubbler in Rm 3109; Sampled faucet	5/19/17 5:10 AM	None Detected
5416-051917-KS-026-B	Flush sample; Sink with bubbler in Rm 3109; Sampled faucet	5/19/17 5:11 AM	None Detected
5416-051917-KS-027-A	Initial Draw sample; Sink with bubbler in Rm 3107; Sampled faucet	5/19/17 5:06 AM	None Detected
5416-051917-KS-027-B	Flush sample; Sink with bubbler in Rm 3107; Sampled faucet	5/19/17 5:07 AM	None Detected
5416-051917-KS-028-A	Initial Draw sample; Sink with bubbler in Rm 3105; Sampled faucet	5/19/17 5:02 AM	None Detected
5416-051917-KS-028-B	Flush sample; Sink with bubbler in Rm 3105; Sampled faucet	5/19/17 5:03 AM	None Detected
5416-051917-KS-029-A	Initial Draw sample; Sink with bubbler in Rm 3005; Sampled faucet	5/19/17 4:54 AM	None Detected
5416-051917-KS-029-B	Flush sample; Sink with bubbler in Rm 3005; Sampled faucet	5/19/17 4:56 AM	None Detected
5416-051917-KS-030-A	Initial Draw sample; Sink with bubbler in Rm 3001; Sampled faucet	5/19/17 4:59 AM	None Detected
5416-051917-KS-030-B	Flush sample; Sink with bubbler in Rm 3001; Sampled faucet	5/19/17 5:00 AM	None Detected
5416-051217-KS-031-A	Initial Draw sample; Sink with bubbler in Rm 3104; Sampled faucet	5/12/17 5:02 AM	None Detected
5416-051217-KS-031-B	Flush sample; Sink with bubbler in Rm 3104; Sampled faucet	5/12/17 5:03 AM	None Detected
5416-051217-KS-032-A	Initial Draw sample; Sink with bubbler in Rm 3108; Sampled faucet	5/12/17 5:05 AM	None Detected
5416-051217-KS-032-B	Flush sample; Sink with bubbler in Rm 3108; Sampled faucet	5/12/17 5:06 AM	None Detected
5416-051217-KS-033-A	Initial Draw sample; Sink with bubbler in Rm 3110; Sampled faucet	5/12/17 5:08 AM	None Detected

**Table 1. Summary of Lead in Drinking Water Laboratory Analytical Results**  
**Peachcrest Elementary School**  
 1530 Joy Lane, Decatur, GA 30032



Sample ID*	Sample Location Description	Sample Date & Time	Lead Test Results (ppb)
5416-051217-KS-033-B	Flush sample; Sink with bubbler in Rm 3110; Sampled faucet	5/12/17 5:09 AM	None Detected
5416-051217-KS-034-A	Initial Draw sample; Sink with bubbler in Rm 3112; Sampled faucet	5/12/17 5:13 AM	None Detected
5416-051217-KS-034-B	Flush sample; Sink with bubbler in Rm 3112; Sampled faucet	5/12/17 5:14 AM	None Detected
5416-051217-KS-035-A	Initial Draw sample; Sink with bubbler in Rm 3201; Sampled faucet	5/12/17 5:15 AM	None Detected
5416-051217-KS-035-B	Flush sample; Sink with bubbler in Rm 3201; Sampled faucet	5/12/17 5:16 AM	None Detected
5416-051217-KS-036-A	Initial Draw sample; Sink with bubbler in Rm 1216; Sampled faucet	5/12/17 5:48 AM	None Detected
5416-051217-KS-036-B	Flush sample; Sink with bubbler in Rm 1216; Sampled faucet	5/12/17 5:49 AM	None Detected
5416-051217-KS-037-A	Initial Draw sample; Sink with bubbler in Rm 1214; Sampled faucet	5/12/17 5:44 AM	None Detected
5416-051217-KS-037-B	Flush sample; Sink with bubbler in Rm 1214; Sampled faucet	5/12/17 5:45 AM	None Detected
5416-051217-KS-038-A	Initial Draw sample; Sink with bubbler in Rm 1212; Sampled faucet	5/12/17 5:41 AM	None Detected
5416-051217-KS-038-B	Flush sample; Sink with bubbler in Rm 1212; Sampled faucet	5/12/17 5:42 AM	None Detected
5416-051217-KS-039-A	Initial Draw sample; Sink with bubbler in Rm 1210; Sampled faucet	5/12/17 5:37 AM	None Detected
5416-051217-KS-039-B	Flush sample; Sink with bubbler in Rm 1210; Sampled faucet	5/12/17 5:38 AM	None Detected
5416-051217-KS-040-A	Initial Draw sample; Sink with bubbler in Rm 1208; Sampled faucet	5/12/17 5:33 AM	None Detected
5416-051217-KS-040-B	Flush sample; Sink with bubbler in Rm 1208; Sampled faucet	5/12/17 5:34 AM	None Detected
5416-051217-KS-041-A	Initial Draw sample; Sink with bubbler in Rm 1206; Sampled faucet	5/12/17 5:30 AM	None Detected
5416-051217-KS-041-B	Flush sample; Sink with bubbler in Rm 1206; Sampled faucet	5/12/17 5:31 AM	None Detected
5416-051217-KS-042-A	Initial Draw sample; Sink with bubbler in Rm 1202; Sampled faucet	5/12/17 5:19 AM	None Detected
5416-051217-KS-042-B	Flush sample; Sink with bubbler in Rm 1202; Sampled faucet	5/12/17 5:20 AM	None Detected
5416-051217-KS-043-A	Initial Draw sample; Sink with bubbler in Rm 1209; Sampled faucet	5/12/17 5:52 AM	None Detected
5416-051217-KS-043-B	Flush sample; Sink with bubbler in Rm 1209; Sampled faucet	5/12/17 5:53 AM	None Detected
5416-051217-KS-044-A	Initial Draw sample; Sink with bubbler in Rm 1213; Sampled faucet	5/12/17 5:56 AM	None Detected
5416-051217-KS-044-B	Flush sample; Sink with bubbler in Rm 1213; Sampled faucet	5/12/17 5:57 AM	None Detected
5416-051217-KS-045-A	Initial Draw sample; Sink with bubbler in Rm 1215; Sampled faucet	5/12/17 5:54 AM	None Detected
5416-051217-KS-045-B	Flush sample; Sink with bubbler in Rm 1215; Sampled faucet	5/12/17 5:55 AM	None Detected
5416-051217-KS-046-A	Initial Draw sample; Sink with bubbler in Rm 1104; Sampled faucet	5/12/17 5:49 AM	None Detected
5416-051217-KS-046-B	Flush sample; Sink with bubbler in Rm 1104; Sampled faucet	5/12/17 5:50 AM	None Detected
5416-051217-KS-047-A	Initial Draw sample; Sink with bubbler in Rm 1102; Sampled faucet	5/12/17 5:45 AM	None Detected
5416-051217-KS-047-B	Flush sample; Sink with bubbler in Rm 1102; Sampled faucet	5/12/17 5:46 AM	None Detected
5416-051217-KS-048-A	Initial Draw sample; Sink with bubbler in Rm 1103; Sampled faucet	5/12/17 5:15 AM	None Detected
5416-051217-KS-048-B	Flush sample; Sink with bubbler in Rm 1103; Sampled faucet	5/12/17 5:16 AM	None Detected



**Table 1. Summary of Lead in Drinking Water Laboratory Analytical Results**  
**Peachcrest Elementary School**  
**1530 Joy Lane, Decatur, GA 30032**



Sample ID*	Sample Location Description	Sample Date & Time	Lead Test Results (ppb)
5416-051217-KS-049-A	Initial Draw sample; Sink with bubbler in Rm 1101; Sampled faucet	5/12/17 5:12 AM	None Detected
5416-051217-KS-049-B	Flush sample; Sink with bubbler in Rm 1101; Sampled faucet	5/12/17 5:13 AM	None Detected
5416-051217-KS-050-A	Initial Draw sample; Sink with bubbler in Rm 1010; Sampled faucet	5/12/17 5:40 AM	1.78
5416-051217-KS-050-B	Flush sample; Sink with bubbler in Rm 1010; Sampled faucet	5/12/17 5:41 AM	None Detected
5416-051217-KS-051-A	Initial Draw sample; Sink with bubbler in Rm 1013; Sampled faucet	5/12/17 5:09 AM	None Detected
5416-051217-KS-051-B	Flush sample; Sink with bubbler in Rm 1013; Sampled faucet	5/12/17 5:10 AM	None Detected
5416-051217-KS-052-A	Initial Draw sample; Sink with bubbler in Rm 1003; Sampled faucet	5/12/17 5:30 AM	None Detected
5416-051217-KS-052-B	Flush sample; Sink with bubbler in Rm 1003; Sampled faucet	5/12/17 5:31 AM	None Detected
5416-051217-KS-052-A2	Initial Draw sample; Sink with bubbler in Rm 1003; Sampled bubbler	5/12/17 5:32 AM	None Detected
5416-051217-KS-052-B2	Flush sample; Sink with bubbler in Rm 1003; Sampled bubbler	5/12/17 5:33 AM	None Detected
5416-051217-KS-053-A	Initial Draw sample; Sink with bubbler in Rm 1001; Sampled faucet	5/12/17 5:24 AM	None Detected
5416-051217-KS-053-B	Flush sample; Sink with bubbler in Rm 1001; Sampled faucet	5/12/17 5:25 AM	None Detected
5416-051217-KS-053-A2	Initial Draw sample; Sink with bubbler in Rm 1001; Sampled bubbler	5/12/17 5:26 AM	None Detected
5416-051217-KS-053-B2	Flush sample; Sink with bubbler in Rm 1001; Sampled bubbler	5/12/17 5:27 AM	None Detected
5416-051217-RS-001-A	Initial Draw sample; Sink on right facing wall closest to door in Boys RR across from Rm 2104	5/12/17 4:57 AM	None Detected
5416-051217-RS-001-B	Flush sample; Sink on right facing wall closest to door in Boys RR across from Rm 2104	5/12/17 4:58 AM	None Detected
5416-051217-RS-002-A	Initial Draw sample; Far left sink in Boys RR Rm 3103	5/12/17 5:35 AM	None Detected
5416-051217-RS-002-B	Flush sample; Far left sink in Boys RR Rm 3103	5/12/17 5:36 AM	None Detected
5416-051217-RS-003-A	Initial Draw sample; Lower left sink in Boys RR Rm 1007	5/12/17 5:35 AM	None Detected
5416-051217-RS-003-B	Flush sample; Lower left sink in Boys RR Rm 1007	5/12/17 5:36 AM	None Detected
5416-051217-TL-001-A	Initial Draw sample; Only sink in Library Media Production Rm 2001.6	5/12/17 5:27 AM	None Detected
5416-051217-TL-001-B	Flush sample; Only sink in Library Media Production Rm 2001.6	5/12/17 5:28 AM	None Detected
5416-051217-TL-002-A	Initial Draw sample; Only sink in Teacher Work Room Rm 2005	5/12/17 5:30 AM	None Detected
5416-051217-TL-002-B	Flush sample; Only sink in Teacher Work Room Rm 2005	5/12/17 5:31 AM	None Detected
5416-051217-CS-001-A	Initial Draw sample; Food Prep sink on north wall of Kitchen closest to Ice Machine	5/12/17 5:02 AM	None Detected
5416-051217-CS-001-B	Flush sample; Food Prep sink on north wall of Kitchen closest to Ice Machine	5/12/17 5:04 AM	None Detected
5416-051217-CS-002-A	Initial Draw sample; Sink on East wall inside Kitchen; Opposite wall from Ice Machine	5/12/17 5:06 AM	None Detected

**Table 1. Summary of Lead in Drinking Water Laboratory Analytical Results**  
**Peachcrest Elementary School**  
 1530 Joy Lane, Decatur, GA 30032



Sample ID*	Sample Location Description	Sample Date & Time	Lead Test Results (ppb)
5416-051217-CS-002-B	Flush sample; Sink on East wall inside Kitchen; Opposite wall from Ice Machine	5/12/17 5:07 AM	None Detected
5416-051217-IM-001-A	Ice Machine on West wall inside Kitchen	5/12/17 5:04 AM	None Detected
5416-051217-SC-001-A	Service Connection Entry into Building	5/12/17 4:58 AM	None Detected

**Notes:**

ppb-parts per billion

**Bold**-Exceeds 15 ppb--EPA's Action Level for Lead

\* Note--Where "A" and "B" are indicated, AEM collected two samples at each source area location: ("A") initial draw sample; and ("B") after a 30-second flush sample